

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

or corners in

Iron
(County)

Located in:

Corner Code #

Public Land Survey

T 43N R 31W

F-11

T R

T R

T R

1. Property Controlling
in Section

S T R

S T R

2. Miscellaneous
Property in Sec.

S T R

S T R

00 DEC 22 PM 3: 26

L.C. Rec'd: L.8, P. 313

Gary L. Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

1. Lot No. , Recorded Plat

2. Private Claims

Quarter Corner Between Sections 28 and 33, T43N, R31W

I, Gary L. Pisoni, in a field survey on November 20, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

1. Description of original monument and accessories and/or subsequent restoration:

Original corner established on July 17, 1849 by John Burt, U.S. Deputy Surveyor.

Original Corner; Ash Post

Original Bearing Trees:

Cedar	10"	N 18° E	28 links (18.48 feet)
Cedar	10"	S 16° W	18 links (11.88 feet)

PEER GROUP APPROVED
Gary L. Pisoni
COUNTY REPRESENTATIVE

2. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

Restored the corner position from a found 1 1/4" diameter iron pipe, 36' South of an East/West pipe line.
Found old blazes near corner position.

I accept the iron pipe as the best available evidence for restoring the corner position.

Corner record research on file with County Representative.

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, set a 5/8" diameter by 30" long rebar pin inside the existing iron pipe with a 3" diameter aluminum cap stamped as follows: Iron County Remonumentation, T43N, R31W, 1/4, S-28, S-33, 2000, RLS 27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Cedar	8"	N 70° E	16.79 feet
Cedar	9"	S 66° E	16.93 feet
Ash	8"	S 27° E	33.17 feet
Cedar	9"	S 27° W	5.74 feet
Steel sign post		South	0.7 feet

00-081

Signed by *Gary L. Pisoni*

Date 12-19-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971
27457 REVISOR MAY 14, 1975
REVISED JAN., 1983
REVISED OCT., 1995



LIBER

8 PAGE 313