LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	Iron	Located In:	Corner Code ≠#	IRON COUNTY, MICH.) "SS
	(County)		0011101 0000 44	RECEIVED FOR RECORD THE 215T DAY OF
				FEBRUARY AD 19 95 AT
1.	Public Land Survey	T 43N R 35W	<u>C-6</u>	The state of the s
		TR		2:45 OCLOCK P M. AND RECORDED IN LIBER OF L.C. LECOLAS
		T B		
		T R		ON PAGE
2	Property Controlling	STR		Much Ochio
۷.		S T R		APUN REGISTER OF DEEDS
_	in Section			33.4.7
3.	Miscellaneous	S T R		Register of Deeds Stamp & File Number
	Property in Sec.	S T R		
		• •		
4.	Lot No, Re	corded Plat	5.84	
5.	Private Claims			ABCDEFGHIJKLM
				2
	Ouarter Corner	S-18, S-17, T43N, F	SO Eta	
	Quarter Corner	3-10, 3-17, 145N, F	CO DM	
	Gary L. Pisoni	:	October 19	94
- I,	1	in a field survey on	, 19	
ao	mereby certify that under requ	rrements of P.M. 74, Michigan P.A	k! Of 1970, the corner points men	ationed 6 18 17 16 15 14 13
CIU	trent manual of europy instruo	conformance with regulations a tions of the United States Depa	nd rules therefore as required	in the
Ma	inagement or by a decree of a (Court of Law and/or that the gore	itment of the interior, Bureau o	of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a				
Court of Law; established, re-established, monumented, re-monumented, recovered, found as				
	pressed below:	- Total and the state of the st	inchamerica, recovered, roo	10 30 29 28 27 28 35
				20 20 20 20 20 20 20 20 20 20 20 20 20 2
IAC	TIE: Not more than 4 cor	ners, all in the same town a	ind range, may be recorded	¹
	on this certificate.			12 -31 -32 -33 -34 -35 -36
		•		13
Α.	Description of original me	onument and accessories ar	d/or subsequent restoration	n:
			#	
	Original corne	r established by Har	d way Mallan II C Don	outy Surveyor in 1851.
	Original corne	re Wood Doct	vey werren, 0.5 beb	ducy surveyor in rear.
	Original beari	_		
	Ceda		S 85 ⁰ W S 79 ⁰ E	4 links(2.64 feet)
	Ceda	r 10"	S 79 €	22 links(14.52 feet)
			**	
		•	i.	
R	Description of corner evid	dence found and/or method	applied in restoring or rees	tablishing corpor:
Ф.			H ₁	
	No evidence of	original corner or h	earing tree remains	corner position found marked
	by a 3/4" x 4"	iron pipe and a 4"x4	" wood post. Corne	er position has been used and
	accepted as the	corner locally for	many years.	*
		-		in the second of
	The corner is a	ccepted as the best	available evidence	of the position of the
	original corner	•		i v
	County Record R	esearch on file with	County Representat	ive office.
	Placed iron nin	e nevt to an aluminu	m nina manumant whi	ich is located 3" above
	around surface	as described below.	in brbe monument with	ich is located 3" above
	ground surrace	as described below.	571	
		:	# * The state of t	PEER GROUP APPROVED
	•			I then Sary I. Proms
				والمستحدد المستحد المستحد المستحد المستحد المستحدد المستح
				COUNTY REPRESENTATIVE
C.	Description of monument	for corner and accessories	established to perpetuale k	ocating the position of the corner: $AP.11-30-94$
-				
	At the corner p	position, I set a 2"	diameter by 30" lo	ng split base aluminum pipe
	monument with a	a 3" cast aluminum c	ap, stamped to read	: Iron County Remonumentation,
	T43N, R35W, 1/4	1, S-18, S-17, 1994,	RLS- 27457 from wh	ich I established the following
	new blazed and	scribed bearing tre	eg: (all mescuremen	nts taken to a nail in side of tree)
		Birch 8"	N 22 E	34.01 feet
	Cedar		S 83°E	
			5 83 E	39.76 feet
	Cedar		s 39°W	40.71 feet 18.10 feet
	Balsa		N 54°W	18.10 feet
	Steel	. Sign Post	North	1.05 feet GARY L.
				PISONI
	,			LAND #
	ned by Adry 1. 7-	/) . :		SURVEYOR
01	and his Asset I	in in	Date /	
sigr	ned by Aday f. /-		Date 17	G 27457 1 1 1
Sun	veyor's Michigan License N	10. 27457		The state of the s
۰ این ب	. 5, 51 5 m. singun bioviiso i	T TO SOLITION TO S		FORM APPROVED BY MICHIGAN STATE BOX OF CHIS SUNVEYORS JOHN 50 1971