

1993

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

IRON COUNTY
MICHIGAN
RECEIVED FOR RECORD
93 DEC 29 PM 2: 22
L.C. RECORDS L-6 P. 308
Gilbert Stiles
REGISTER OF DEEDS

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T 43N R 35W	E-5
	T R	
	T R	
	T R	
2. Property Controlling in Section	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Section Corner 8-9-16-17 T43N R35W

I, Gary L. Pisoni, in a field survey on December 21, 19 93, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established by Harvey Mellen, U.S. Deputy Surveyor on August 28, 1851.

Original corner: Wood Post

Original bearing trees: Sugar Maple 12" N 12°W 17 links (11.22 feet)
White Pine 30" S 45°W 28 links (18.48 feet)

In 1935, timber and acquisition crews for the U.S.F.S. placed a U.S.F.S. metal location tag on the North side of a maple tree from which the corner lays Northeast 11 links.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Restored corner position at record bearing and distance from an original bearing tree; a partially decayed 38" White Pine stump bears S 45°W, 18.48 feet from the original corner location; no other evidence of other bearing tree found. At the original corner location, found a 3½"x2½"x16" partial remains of a wood post lying on the ground next to an axle shaft which is at the correct bearing and distance from the White Pine bearing tree.

Recovered 1935 U.S.F.S. acquisition crew tag located on the North side of a 10' stub, 24" dia. maple tree bearing S 67°W, 7.7 feet from the original corner location (can only read date on tag, name on tag illegible due to rusty portion of tag).

Old fence lines (wire) lying on the ground run North, South, East, and West from the axle shaft
Placed axle shaft inside of monument as described below.

Corner is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

At the corner position, I set a standard 2" diameter by 30" long split base aluminum pipe monument with a 3" cast aluminum cap, stamped to read: T43N, R35W, S-8, S-9, S-16, S-17, 1990. RLS-27457 from which I established the following new blazed and scribed bearing trees: (all measurements taken to a nail in side of tree)

Sugar Maple	8"	N 73°E	6.78 feet
Sugar Maple	7"	S 55°E	26.62 feet
Sugar Maple	7"	S 03°30'E	34.69 feet
Steel Sign Post		N 53°W	0.95 feet



Signed by Gary L. Pisoni Date 12-28-93

Surveyor's Michigan License No. 27457