MAR + 9 2000

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Iron (County)	Located In:	Corner Code #	IRON COUNTY MICHIGAN RECEIVED FOR RECORD
1. Public Land Survey	T <u>43N</u> R <u>35W</u> T <u>43N</u> R <u>34W</u> TR	M-11 A-11	99 DEC 30 AMIO: 33 L.C. Records: L.8, P. 130
2. Property Controlling S_ in Section S_ 3. Miscellaneous S_	TR TR TR		Tolken Tales
Property in Sec. S_	TR		Register of Deeds Stamp & File Number
4. Lot No, Records 5. Private Claims			- A B C D E F G H I J K L M
Section Corner to Sections 25 and 36, T43N, R35W Section Corner to Sections 30 and 31, T43N, R34W			3
that under requirements of P.A. in lines 1 and 2 above were in required in the current manual of the Interior, Bureau of Land Mana corner points mentioned in lines the Michigan Board of Land Sur re-established, monumented, reco	74, Michigan P.A. of 197 conformance with regular survey instructions of the gement or by a decree of 3, 4 and 5 above were inveyors or by a Decree covered, found as expressions.	70, the corner points mention ulations and rules therefore he United States Department of a Court of Law and for that n conformance with the rules of a Court of Law; establish ed below:	as 7
NOTE: Not more than 2 corners, all on this certificate.	l in the same town and ran	ge, may be recorded	12 -31 -32 -33 - 34 -35 -36
A. Description of original monutory Original corner established or Original Corner; Fir Post Original Bearing Trees: Sugar Yellow Birch In 1978, Gary L. Pisoni, RLS corner position.	14" N 71 °E	38 lks (25.08 feet)	PEER GROUP APPROVED TRan Nay & Loca 12-21-27 COUNTY REPRESENTATIVE nehl Road which runs East and West marking the
•	nce found and/or method	applied in restoring or reesta	ablishing corner:
No evidence of original B.T.			
Iron pipe has been used for top of the existing pipe. So the corner position.	many surveys in the sur at a P.K. nail over the top	rounding area. In recent year o of existing pipe. I accept th	ars, a new layer of asphalt has been laid over the ne pipe as the best available evidence for restoring
Corner record research on f			
			cating the position of the corner:
Iron County Remonumentati which I established the follo Fire Hydrant	ion, T43N, R35W, R34W owing new blazed and so N 28 5/8" x 30" rebar North M87-2 S 62 M87-1 S 66	7, R.M., S-25, S-30, S-36, S- ribed bearing trees: (All measing trees) 31.55 feet 30.11 feet E 62.48 feet W 75.01 feet	th a 3" diameter aluminum cap stamped as follows: 31, South, 30.11 feet, 1999, RLS 27457 from surements taken to a nail in side of tree) OF MICHICAL PISONI LAND
99-130 Signed by Way I fu	<i>son</i> Da	ite 12.28-95	SURVEYOR No.
Surveyor's Michigan License No	27457	FORM APPROVED	BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971 PRINCIPLE MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995