

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
	S 12 T 44N R 32W	15
2. Property Controlling	S 12 T 44N R 32W	10
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File
Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on Jan 17, 2008 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 12) West 1/16 corner between Sections 12 and 13. 1989 - Established by K.L.Sackett RLS midway and on line between Section corner to west and computed position for 1/4 corner to east. Set 1"IDx32" I.pipe with 4" aluminum cap. 6" Balsam N60W 9.9', 7" Spruce N63E 39.1', 4" Spruce S25E 28.6'.

(10-Sec. 12) South 1/16 between Sections 11 and 12. 1989 - Established by K.L.Sackett RLS midway and on line between Section and Quarter corners. Set 1"x36" I.pipe with 4" aluminum cap. 8" Spruce N55W 8.8', 6" Spruce S29W 19.4', 7" Spruce N54E 16.5'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(15-Sec. 12) 1999 - found the 1989 monument disturbed, laying down and bent. Removed the monument, straightened it, and reset it in the 1989 position, at record bearing and distance from the Balsam BT NW and the Spruce BT NE, both cut stumps. The Spruce BT SE was dead and down. Made new witness 3" Balsam N35W 37.0'. 2008 - Recovered the same monument in good condition and at record bearing and distance from the 1999 NBT Balsam N35W, now 6" DBH in good condition.

(10-Sec. 12) Recovered the 1989 monument in good condition, at the record position, and at record bearing and distance from the 1989 witnesses, now all dead and down. Accepted same as a careful and faithful establishment of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(15) Fd. 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
4" Balsam S26W 77.95' mrkd "1/16S BT"
7" Balsam S63W 69.2' do
12" Tamarack N55W 76.9' do
6" Balsam N35W 37.2' do
Bearings are magnetic. Set sq'd post adjacent.

(10) Fd. 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
6" B.Spruce N01E 15.9' mrkd "1/16S BT"
6" B.Spruce S22E 10.5' do
5" B.Spruce S24W 19.6' do
4" B.Spruce N79W 17.8' do
Bearings are magnetic. Set sq'd post adjacent.

Signed by

Stephan J. Szyszkoski



Date

1/22/08

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS