

SURVEY & REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

00 DEC -5 PM 12:50

L.C. Records: L. 8, P. 117

Robert A. Goodreau
REGISTERED PROFESSIONAL SURVEYOR

For corners in

<u>Iron</u>	Located In:	Corner Code #
(County)		
1. Public Land Survey	T 44N R 33W	K-3
	T R	
	T R	
	T R	
	T R	
2. Property Controlling	S T R	
in Section	S T R	
3. Miscellaneous	S T R	
Property in Sec.	S T R	

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, Robert A. Goodreau in a field survey on May 16, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2				1
3													
4	7		8		9		10		11				12
5													
6	18		17		16		15		14				13
7													
8	19		20		21		22		23				24
9													
10	30		29		28		27		26				25
11													
12	31		32		33		34		35				36
13													

A. Description of original monument and accessories and/or subsequent restoration:

K-3 Original corner established by Guy A. Carleton, U.S. Deputy Surveyor, in June 1851.

Original witnesses:	Tamarack	8	N73E	24 links
	Spruce	9	S80W	33 links

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

K-3 Found 1" iron pipe w/ 4" brass cap set by Billy D. Buckler RLS, using double proportionate measurement from corners in 4 directions, on 7 June 1959 (Liber 2, Page 187).

Found witnesses recorded by Buckler as:	5" Cedar	S88E	18.5 links
	5" Tamarack	N75W	25 links
	9" Cedar	S12E	62 links

PEER GROUP APPROVED
Ken Ray D. Lane 11-14-2000
COUNTY REPRESENTATIVE

Corner record research on file with county representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-3 Accepted corner as found.

Witnesses:	9" Tamarack	N 70° W	17.67'
	10" Cedar	N 72° E	19.17'
	10" Cedar	S 72° E	12.71'
	10" Cedar	S 28° E	38.98'
	Sign post	North	1'

Note: Measurements taken to a nail in side of witnesses.

Signed by *Robert A. Goodreau*
Surveyor's Michigan License No. 43053

Date July 1, 2000

