

# SURVEY & REMONUMENTATION

FEB 21 2001

## SECTION

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Iron  
(County)

Located In:

Corner Code #

1. Public Land Survey

T 44N R 34W

B-5

T      R     

T      R     

T      R     

2. Property Controlling  
in Section

S      T      R     

S      T      R     

3. Miscellaneous  
Property in Sec.

S      T      R     

S      T      R     

COMMENCING YEAR 2000  
RECEIVED FOR RECORD  
IRON COUNTY, MICHIGAN

00 DEC -8 PM 12:59

*L.C. Records 1.8, P. 233*

*Gilbert L. Pisoni*  
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No.         , Recorded Plat         

5. Private Claims         

Quarter Corner to Sections 7 and 18, T44N, R34W

I, Gary L. Pisoni, in a field survey on March 18, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established on August 19, 1851 by Guy H. Carleton, U.S. Deputy Surveyor.

Original Corner; Wood Post

Original Bearing Trees:

Yellow Birch	10"	S 65° W	15 links (9.90 feet)
Cedar	10"	N 45° E	41 links (27.06 feet)

On 11/3/76, Arthur O. Enger RLS DNR re-established the quarter corner by proportionate measurement and on line between the SW and SE Section corners of Section 7 and set a 1" dia. x 36" iron pipe with a 3 3/4" dia. aluminum cap stamped as follows: T44N, R34W, 1/4, S-7, S-18, 11/3/76, RLS 13581. Recorded in Liber 1, Page 513 of LC records

1976 Bearing Trees:

Cedar	6"	N 26° W	7.5 feet
Cedar	7"	S 19° E	2.3 feet
Cedar	8"	N 23° E	4.4 feet

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 3/18/2000, found monument as described above and the following bearing trees:

Cedar	7"	N 21° W	7.91 feet
Cedar	10"	N 29° E	4.68 feet
Cedar	10"	S 10° E	2.61 feet

Monument is 10" above ground surface.

Corner record research on file with County Representative.

PEER GROUP APPROVED

*Iron County Rep. 11-30-2000*  
COUNTY REPRESENTATIVE

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing tree: (All measurements taken to a nail in side of tree)

Cedar	9"	N 49° W	7.12 feet
Steel sign post		S 65° W	0.65 feet

00-001

Signed by

*Gary L. Pisoni*

Date

11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 30, 1971

