

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 6 T 45N R 31W	5
	S 6 T 45N R 31W	6
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1		6											
2				5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 02/28/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(5-Sec. 6) North 1/16 corner, Section 6. Not previously monumented.

(6-Sec. 6) Northeast 1/16 corner, Section 6. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(5-Sec. 6) Established the position for the corner on a straight line between Quarter corner B1
1290.29' north and the intersection of 1/4 lines of Section 6 1319.31' south, being proportionate to
the dimensions derived from the original plat of this township (19.56 chains and 20.00 chains,
respectively).

(6-Sec. 6) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners. From the position thus established, I found a 3/4" ID iron pipe, not of
record, N23°W 17.4' distant, which I did not accept as marking the position for the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(5) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
12" Sugar S34°E 7.9' mrkd "1/16S BT"
11" Maple S24°W 8.0' do
7" Sugar N54°W 22.5' do
7" Sugar N14°W 7.15' do
Set sq'd cedar post adjacent.

(6) Set 1"IDx32" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Sugar N32°E 25.8' mrkd "1/16S BT"
9" Sugar South 25.9' do
9" Sugar S64°W 21.2' do
4" Sugar N35°W 12.4' do
Set sq'd cedar post adjacent.

Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 08/01/2013

For the Michigan Department of Natural Resources, Forest Resources Division

