## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For	co	rn	erc	in
I UI	LU	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	C12	

Iron (County)	Located In:	Corner Code #	
1. Public Land Survey	TR		
2. Property Controlling in Section	S 24 T 45N R 31W S T R S 24 T 45N R 31W	11 (GCDB 620320)	
3. Miscellaneous Property in Sec.	S T R R S T R	15 (GCDB 620300)	Posterio (P. 1. C.
4. Lot No. , Re 5. Private Claims	corded Plat		Register of Deeds Stamp & File Number  A B C D E F G K I J K L M  2 6 5 4 4 3 2 2 1 1
above were in conformance with	74, Michigan P.A. of 1970, the corner regulations and rules therefore as require	ed in the current manual of survey	,5 <del> </del>
a Court of Law and /or that the	Department of the Interior, Bureau of Lacorner points mentioned in lines 3, 4 and of of Land Surveyors or by a Decree vered, found as expressed below:	5 above were in conformance with	, 7 <del>                                   </del>
NOTE: Not more than 2 corr on this certificate.	ners, all in the same town and range	, may be recorded	10 30 29 28 27 26 25 11 12 31 32 33 34 35 36

A. Description of original monument and accessories and/or subsequent restoration:

(15-Sec. 24) West 1/16 corner between Sections 24 and 25. Found no record of monumentation.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(11-Sec. 24) Southwest 1/16 corner, Section 24. Not previously monumented.

(11-Sec. 24) Established the position for the corner at the intersection of straight lines connecting opposite 1/16 corners, all monumented.

(15-Sec. 24) The position for the corner is midway and on the Section line between Section corner 1314.54' west and Quarter corner 1314.54' east. Substantially at this position, 0.06' east and 0.13' north from it, I found a 1/2" rebar projecting 2.5" above ground, set by an unknown surveyor, which I accepted as a careful and faithful determination of the position of the corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(11) Set 1"IDx28" I.pipe with 2" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:	(15) Found 1/2" uncapped rebar. Set measuring nail with MDNR tag in the side of:
10" B.Spruce N04°W 17.8' mrkd "1/16S BT"	5" Balsam N20°E 14.1' mrkd "1/16S BT"
14" Cedar S63°E 14.4' do	5" Balsam S80°E 7.6' do
6" Balsam S62°W 11.3' do	3" Balsam S08°W 9.2' do
8" Balsam N51°W 22.05' do	6" Balsam N63°W 9.7' do
Set sq'd cedar post adjacent.	Set sq'd cedar post adjacent.
E= 7912689.506 N= 166855.858	E= 7912680.862 N= 166451.305

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.

Coord. Ref.=NGS PID RL0202: N= 156159.364 m. E= 7917031.370 m.

Signed by Stake	I Landy hoole	Date	04/25/2016	
Surveyor's Michigan License No.	33986			

STEPHAN J. SZYSZKOSKI LAND

LAND

RVEYOR