

LAND CORNER RECORDATION CERTIFICATE

Authority: 1970 PA 74, MCL 54.205

Surveyor's Name: Stephan J. Szyszkoski

Field Survey Date: 5/26/16 - 5/31/16

For corner(s) in: Iron County

Original Public Land Survey Corner

Corner Code

a. S 45N R 31W T 45N R 31W K06 (GCDB 600440)
S T R
S T R
S T R

Property Corner

1/16 Corner Code

b. S 11 T 45N R 31W 15 (GCDB 520500)
S 14 T 45N R 31W 1 (GCDB 520500)
S T R
S T R

1	A	B	C	D	E	F	G	H	I	J	K	L	M	1
2	6		5		4		3		2		1		2	
3													3	
4	7		8		9		10		11		12		4	
5													5	
6	18		17		16		15		14		13		6	
7													7	
8	19		20		21		22		23		24		8	
9													9	
10	30		29		28		27		26		25		10	
11													11	
12	31		32		33		34		35		36		12	
13													13	
	A	B	C	D	E	F	G	H	I	J	K	L	M	

Part A. Corner History

a.) Quarter corner common to Sections 13 and 14. 1980 - Reestablished by K.L.Sackett RLS on the Section line between Section corners 40.00 chains south and 41.00 chains north (after concluding that the original survey contained a blunder in the north 1/2 mile). Set 1"IDx32" iron pipe with 4" aluminum cap. 8" Spruce S37°E 30.8', 7" Spruce S54°W 32.4'.

b.) West 1/16 corner between Sections 11 and 14. 1980 - Established by K.L.Sackett RLS midway between corners E & W. Set 1"IDx36" iron pipe with 3-1/2" aluminum cap. 6" Spruce N35°E 48.6', 26" R.Pine S08°W 73.7'.

Part B: Surveyor's Report on Perpetuation, Restoration, Reestablishment, or Monumentation of Corner

a.) Found the 1980 monument in good condition and substantially at the 1980 position of record. The 1980 witnesses are no longer present. Accepted the monument as a careful and faithful restabishment of the position of the original corner.

b.) Found the 1980 monument of record, in good condition and substantially at the position of record. Accepted same as a careful and faithful determination of the position of the corner.

Part C: Field Evidence of Perpetuation or Monumentation of Corner

(a.) Found 1"ID I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
8" Balsam N20°W 6.0' mrkd "1/4S NBT"
3" Spruce N48°E 9.0' do
9" Poplar S34°E 5.5' do
4" Balsam N77°W 9.85' do
E= 7912328.418 N= 168828.744

(b.) Fd. 1"ID I.pipe with 3-1/2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Tamarack N44°E 19.65' mrkd "1/16S BT"
9" Poplar S42°E 21.2' do
4" Poplar S06°W 7.2' do
4" Poplar N84°W 10.7' do
Existing cedar post adjacent.
E= 7911142.566 N= 169670.561

Bearings are magnetic. Coordinates are MCS83, NAD83(2011) Epoch 2010.00, in meters
Coordinate Reference: NGS PID RL0202, E= 7917031.357 m. N= 156159.387 m.

Stephan J. Szyszkoski

08/23/2016

Professional Surveyor's License No.: 33986

page 1 of 1

Prepared By: S.J. Szyszkoski for the Michigan Dept. of Natural Resources, 427 N. US41 Baraga, MI 49908

