

LAND CORNER RECORDATION CERTIFICATE

FILING REQUIREMENT OF ACT 74, MICH. P.A.1970

FOR CORNERS OF—	LOCATED IN—	CORNER CODE NUMBER
1. PUBLIC LAND SURVEY _____ T. <u>45</u> N. <u>34</u> W.		<u>D11</u>
2. PROPERTY CONTROL- <u>32</u> ING IN SECTION _____ T. <u>45</u> N. <u>34</u> W.		<u>2, 15a & 15b</u>
3. MISCELLANEOUS PROPERTY IN SECTION _____ T. _____ N. _____ W.		
4. LOT NO. _____, RECORDED PLAT _____		
5. PRIVATE CLAIMS _____		

REGISTER OF DEEDS STAMP AND
FILING NUMBER

I, Arthur O. Enger do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above (identified with circles on index code diagram—over) were, in a field survey on see below 19____, established, re-established, monumented, re-monumented, recovered or restored as expressed below and in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a court of law. Furthermore, that the corner points mentioned in lines 3, 4 and 5 above were, in a field survey on _____ 19____, found, recovered, restored, established or re-established as expressed below and in conformance with the rules of the Michigan State Board of Registration for Land Surveyors or, by a Decree of a Court of law:

A. Description of original monument and accessories and/or subsequent restoration:

Corners D11, 15a, & 15b: Found no evidence of original posts or accessories or of any replacement monuments or accessories.

Corner 2: Not established in original survey nor subsequently, apparently.

B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:

Corner D11: Re-established 8/22/73 on line between Sec. Cor. 39.940 ch. E and 38.920 ch. W. Difference in distances is believed to represent original survey error in determining the distance across the Net River in the W half-mile of this line; probably was estimated rather than measured.

Corner 15a: Re-established 9/3/74 on E bank of Net River, proportionately on true sec. line 16.961 ch. E of 1/4 cor. and 23.065 ch. W of Sec. Cor.

Corner 15b: Re-established 8/23/74 on true sec. line on W bank of Net River, 18.432 ch. E of Sec. Cor. and 21.595 ch. W of 1/4 cor.

Corner 2: Established 8/27/73 on line between 1/4 cor. 19.970 ch. W and Sec. Cor.

19.970 ch. E.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Corner D11: 1" I.D. x 36" iron pipe with 4" aluminum cap.

W. Spruce 8 N8½°E (mag.) 16.6 ft. "1/4S, NBT"

W. Pine 16 S55°W (mag.) 27.2 ft. "1/4S, NBT"

Monuments for Corners 2, 15a & 15b: 1" I.D. x 36" iron pipe with 3½" aluminum cap.

Witnesses for Corner 15a: B. Ash 8 N60°E (mag.) 30.9 ft. "M.C., NBT"

Elm 36 S50°E (mag.) 68.0 ft. "M.C., NBT"

Witnesses for Corner 15b: Cedar 13 N½°E (mag.) 24.4 ft. "M.C., NBT"

Cedar 6 N89°W (mag.) 37.4 ft. "M.C., NBT"

Witnesses for Corner 2: Sugar Maple 6 S57½°W (mag.) 22.5 ft. "1/16S, BT"

Red Maple 5 N87½°E (mag.) 4.2 ft. "1/16S, BT"

SIGNED BY _____ DATE _____

SURVEYOR'S MICHIGAN REGISTRATION NO. _____

(SEAL)

FOR STATE AND UNITED STATES AGENCIES:

SIGNED BY _____ DATE _____

APPROVED AND SIGNED BY _____ DATE _____

Arthur O. Enger

Michigan Department of Natural Resources

SURVEYOR'S MICHIGAN REGISTRATION NO. 13581

