

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 4 T 45N R 34W	4
	S T R	(GCDB 320660)
	S 4 T 45N R 34W	F2
3. Miscellaneous Property in Sec.	S T R	(GCDB 340640)
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5			4		3		2		1	
3													
4	7		8			9		10		11		12	
5													
6	18		17			16		15		14		13	
7													
8	19		20			21		22		23		24	
9													
10	30		29			28		27		26		25	
11													
12	31		32			33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on F2 08/25/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(4-Sec. 4) Northwest 1/16 corner, Section 4. Not previously monumented.

(F2) Center of Section 4. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(4-Sec. 4) A subdivision of the NW1/4 of this section could be made in several ways and the choice
of methods is more complicated than normal due to the lack of harmony between conditions on the
ground and their representation on the face of the U.S. plat. I found a 5/8" rebar with no cap,
placed previously by Gary L. Pisoni PS #27457 and accepted same as a careful and faithful
determination of the position of the corner.

(F2) Established the position for the corner at the intersection of 1/4 lines. The N-S 1/4 line is
a straight line between 1/4 corners F1 and F3. The E-W 1/4 line is parallel to the weighted mean
bearing of the two lines G3-F3 and F3-E3.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(4) Drove a 1"IDx28" I.pipe with 2" alum. MDNR cap
over the top of the found 5/8" rebar.
Set measuring nail with MDNR tag in the side of:
6" Sugar N43°E 11.0' mrkd "1/16S BT"
4" Sugar N86°E 6.05' do
10" Sugar S35°W 28.7' do
10" Sugar N34°W 11.6' overgrown blazes
Set sq'd cedar post adjacent.
E= 7879126.910 N= 173058.065

(F2) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Sugar N59°E 20.8' mrkd "C1/4 BT"
9" Sugar S34°E 19.65' do
8" Sugar N84°W 10.1' do
9" Sugar N09°W 36.6' do
Set sq'd cedar post adjacent.
E= 7879522.313 N= 172659.680

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.411 m. E= 7879234.516 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 09/15/2015

For the Michigan Department of Natural Resources, Forest Resources Division