

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T _____ R _____	_____
	T _____ R _____	_____
	T _____ R _____	_____
2. Property Controlling in Section	S 30 T 45N R 34W	13
	S 30 T 45N R 34W	5
	S _____ T _____ R _____	_____
3. Miscellaneous Property in Sec.	S _____ T _____ R _____	_____
	S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

I, Stephan J. Szyszkoski, in a field survey on 13 10/12/2009 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(13-Sec. 30) Southeast 1/16 corner, Section 30. Not established in the original survey.

(5-Sec. 30) North 1/16 corner, Section 30. Not established in the original survey. Found no subsequent record.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(13-Sec. 30) Established the corner at the intersection of straight lines connecting opposite 1/16 corners.

(5-Sec. 30) Established the corner midway and on a straight line between Quarter corner 1319.72' north and the intersection of 1/4 lines of Section 30 1319.72' south. At the position for the corner, I found a 5/8" dia. uncapped rebar, set firm, projecting 3" above grade. Accepted same as a careful and faithful establishment of the position of the corner and placed a plastic MDNR cap on top of the rebar.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(13) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
5" Balsam N30E 95.26' mrkd "1/16S BT"
15" Spruce S55E 52.18' do
3" Balsam S08E 50.52' do
Sq'd Cedar post N03E 0.95' to center.
Bearings are magnetic.

(5) Fd 5/8" rebar. Placed plastic MDNR cap atop. Set measuring nail with MDNR tag in the side of:
13" Maple N28W 1.9' mrkd "1/16S BT"
8" Sugar N79E 31.1' do
6" Sugar S61E 24.1' do
8" Maple S67W 10.9' do
Set sq'd cedar post adjacent.
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 11/02/2009

For the Michigan Department of Natural Resources, Office of Land and Facilities

