

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron	Located In:	Corner Code #
(County)		
1. Public Land Survey	T46N R 31W	L9
	T R	
	T R	
2. Property Controlling in Section	S25 T46N R 31W	L10
	S T R	
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims

L10 Mar 03 2008
L9 Feb 28 2008

I, Stephan J. Szyszkoski, in a field survey on _____, 20____ do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(L9) Quarter corner common to Sections 24 and 25. 1986 - Reestablished by single proportionate measurement to the original record, midway and on the Section line between K9 and M9, by K.L.Sackett RLS. Set 1"IDx36" I.pipe with plastic cap # 19006. 5" Spruce N20E 25.5', 12" W.Birch S72W 49.6', 4" sq'd maple with poster S01W 1.9'.

(L10) Center of Section 25. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(L9) Recovered the 1986 monument as described, at record bearing and distance from the W.Birch NBT S79W. The other two 1986 NBTs were not visible above the snow. The monument was found to be at the proportionate position of record. Accepted the monument as a careful and faithful reestablishment of the position of the original corner.

(L10) Established the corner at the intersection of straight lines connecting opposite 1/4 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(L9) Found 1"ID I.pipe with plastic cap # 19006. Set measuring nail with MDNR tag in the side of:
2" Spruce N79E 22.4' mrkd "1/4S NBT"
4" Poplar S64E 21.5' do
3" Balsam N25W 6.9' do
10" W.Birch S79W 50.4' old scribing (1986 NBT)
Sq'd cedar post adjacent. Bearings magnetic.

(L10) Set 1"IDx32" I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
8" B.Spruce N28E 11.2' mrkd "C1/4 BT"
4" B.Spruce N52E 11.15' do
9" B.Spruce S50E 24.5' do
6" B.Spruce N33W 8.7' do
Sq'd cedar post adjacent. Bearings magnetic.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26				
11													
12	31		32		33		34		35		36		
13													

Signed by

Stephan J. Szyszkoski



Date

3/5/08

Surveyor's Michigan License No.

33986

For the Michigan Department of Natural Resources, Office of Land and Facilities

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS