

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Iron (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____ _____ _____
2. Property Controlling in Section	S 13 T 46N R 34W S _____ T _____ R _____ S 24 T 46N R 34W	8 (GCDB 620440) 3
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	(GCDB 600360) _____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

I, Stephan J. Szyszkoski, in a field survey on 01/25/16 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
Instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 13) Center-West 1/16 corner, Section 13.
Found no record of prior monumentation.

(3-Sec. 24) North 1/16 corner between Sections 23 and 24.
Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 13) Established the position for the corner midway and on a straight line between Quarter
corner K6 1318.62' west and unmonumented L6 (intersection of 1/4 lines) 1318.62' east. From the
position thus established, I found a 1" iron pipe, by persons unknown, N73°E 9.4' distant, not
accepted, and subsequently removed.

(3-Sec. 24) Established the position for the corner midway and on the Section line between Section
corner K7 1320.85' north and Quarter corner K8 1320.85' south.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
9" B.Spruce N17°W 24.9' mrkd "1/16S BT"
10" B.Spruce S66°E 9.0' do
7" B.Spruce S50°E 5.1' do
6" Balsam S13°W 12.7' do
Set sq'd cedar post adjacent.
E= 7884087.727 N= 179025.238

(3) Set 1"IDx28" I.pipe with 2" alum. MDNR cap
Set measuring nail with MDNR tag in the side of:
6" Balsam N20°E 7.55' mrkd "1/16S BT"
11" Maple N66°E 12.7' do
7" Maple S59°E 17.1' do
5" B.Spruce S75°W 7.65' do
Set sq'd cedar post adjacent.
E= 7883660.585 N= 177828.504

Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RL0476: N= 196482.409 m. E= 7879234.515 m.

Signed by Stephan J. Szyszkoski Date 02/17/2016
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

