

SURVEY &
REMONUMENTATION

FEB 21 2001

SECTION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

COMMENCING YEAR 2000
RECEIVED FOR RECORD
IRON COUNTY, MICHIGAN

For corners in

_____ Iron _____ Located In: _____ Corner Code # _____
(County)

1. Public Land Survey T 46N R 35W I-11
T _____ R _____
T _____ R _____
T _____ R _____

2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____

3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

00 DEC -8 PM 1:04
L.C. Record: L.S. P. 25.
Gilbert Pisoni
REGISTERED LAND SURVEYOR

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____
5. Private Claims _____

Section Corner to Sections 26, 27, 34 and 35, T46N, R35W

I, Gary L. Pisoni, in a field survey on September 12, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5				4		3		2		1	
3													
4	7	8				9		10		11		12	
5													
6	18	17				16		15		14		13	
7													
8	19	20				21		22		23		24	
9													
10	30	29				28		27		26		25	
11													
12	31	32				33		34		35		36	
13													

A. Description of original monument and accessories and/or subsequent restoration:

Original corner established in 1851 by Harvey Mellen, U.S. Deputy Surveyor.
Original Corner; Wood Post
Original Bearing Trees:

Spruce	18"	N 36 E	36 links (23.76 feet)
Hemlock	16"	S 74 W	27 links (17.82 feet)

On 4/28/69, Donald D. Lappala RLS USFS restored the corner position from a found wood post at record bearing and distance from the remains of the original bearing trees. Set a 2" diameter by 5' long iron pipe with a 3" diameter bronze tablet stamped as follows: T46N, R35W, S-26, S-27, S-34, S-35, 1969, RLS 12585, recorded in Liber 3, Page 210 of LC records.

1969 Bearing Trees:

Black Spruce	7"	N 65 E	34.7 feet
White Spruce	6"	S 28 E	4.5 feet
Black Spruce	7"	S 60 W	19.4 feet

PEER GROUP APPROVED
Gary L. Pisoni 11-30-00
COUNTY REPRESENTATIVE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

No evidence of original B.T.s found.

On 9/12/2000, found the above described monument and the following bearing tree:

Black Spruce	8"	S 52 E	4.45 feet
--------------	----	--------	-----------

Found existing bearing tree established by the U.S.F.S.:

Red Maple	8"	N 74 W	15.98 feet
Steel sign post		N 81 E	2.3 feet

Monument is 24" above ground surface.

Corner record research on file with County Representative.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Blazed and scribed the following new bearing trees: (All measurements taken to a nail in side of tree)

Black Spruce	10"	S 44 W	29.25 feet
Balsam	6"	N 23 E	25.26 feet

00-026

Signed by Gary L. Pisoni Date 11-13-2000

Surveyor's Michigan License No. 27457

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1992
REVISED MAY 13, 1993
REVISED JAN. 1993
REVISED DEC. 1995

