COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE	OF MICHIGAN	į
RECEIP)

Nov 30 | | 31 AM '93 000002

Helle L. Hilmore REGISTER OF DEEDS


	r corners in sabella	R)	EMONUMENTATION Corner Code =##
	(County)		
1.	Public Land Survey	14N 3W T R	(A6),8-4
		T R	
		T R	Deg #1
		T R	<i>U</i>
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	S T R	

Register of Deeds Stamp & File Number

Private Claims				1.7
		:		H.
Norman C. Caldwell	, in a field survey on	July	19	93

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.



Description of original monument and accessories and/or subsequent restoration:

West 1/4 Cor. Sec.18, T14N-R3W

This position not established by original government survey.

L.C.R.C. by W. Ruddell, Recorded in Bk.1 P.187, Found 39mm Iron Pipe: NW 8.23M T. Pole; NE 22.34M 45.5cm Tree; North 23.256M M-6, T14N-R4W

L.C.R.C. by J. Radcliffe, Recorded in Bk. 1 P.275, Found 39mm Pipe 30.5cm deep, Placed 16mm x 45.5cm Rod in Center of Pipe: \$85°E 9.833M Fnc Post; West 8.202M P. Pole; N50°E 16.752M 25.5cm Willow.

L.C.R.C. by W. Ruddell, Recorded in Bk. 2 P.508. Found Iron Pipe: NW 8.23M T. Pole; NE 22.342M 45.5cm Tree.

Survey by: book 4 P. 98 Ruddell L.1 P.516 & Co. Surv. record

(B-4) Center 1/4 Cor. Sec. 7, T14N-R3W

This position not established by original government survey.

L.C.R.C. by W. Ruddell, Recorded in Bk.2 P.587, Found 20mm Pipe: WSW 16.86M 25.5cm Ash; SE 10.21M 20cm Apple: ENE 25.039M 30.5cm Oak.

Surveys by: Ruddell L.3 P.378, Fokens L.40-209 County Surveyors book 3, P.72

STATE OF MICHIGA NORMAN C. CALDIVELL PROFESSIONAL SURVEYOR A OF ESSIONAL MANAGEMENT OF THE STATE OF THE

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

West 1/4 Cor, Sec.18, T14N-R3W

Found Tee Iron in Mon. Box (Origin Unknown)

Center 1/4 Cor. Sec.7, T14N-R3W

Found 20mm Iron Pipe per Bk. 2 P. 587,

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

West 1/4 cor. Sec. 18, T14N-R3W

Fnd Tee iron in Mon. Box, origin unknown, and is accepted as a careful and faithful determination of the position of the corner.

\$87°₩ 8.465M T. Pole 45.5cm Maple 34.792M N37°E 22.285M N44°W 11.000M 76 cm Willow N44°W Top of guy anchor

23.272M

52mm Iron pipe in Mon. box (R) (E 1/4 Sec. 13, T14N-R4W)

(B-4)Center 1/4 Cor. Sec.7, T14N-R3W

fnd 20mm from pipe per Bk. 2 P.587 and is accepted as a careful and faithful determination of the position of the corner.

N81°E 25.040M S55°E 33.300M 30.5cm B. Oak 18cm Boxelder S05°W 11.670M N20°E 11.164M 13cm B. Oak 15cm Elm

26 NOV 93

Surveyor's Michigan License No.

Signed by

2018

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971' REVISED MAY 14, 1975 REVISED JAN., 1983