MAY 0 5 1997

17204

COMMISSION REMONUMENTATION CORNER

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

TATE OF MICHIGAN COUNTY OF ISABELLA RECEIVED SECOND RECORD

Jan 23 1 20 PM 197

10

30

10

11

12

corner:

21

28

ACCEPTED BY THE ISABELLA COUNTY. REMONUMENTATION PEER GROUP.

ON DOG

William B. Ruddell, PS

County Representative

20

29

32

22

27

1996

23

24

25

Isabella (County)	Located In:	Corner Code #	OOO164 SHARON A. BROWN REGISTER OF DEEDS
1. Public Land Survey	T_14N R_6W T R T R	<u>K-6</u>	- COLUMNIA DE LE COLUMNIA DE LA COLUMNIA DEL COLUMNIA DEL COLUMNIA DE LA COLUMNIA
 Property Controlling in Section Miscellaneous SProperty in Sec. 	T R R T R R T R R T R R R R R R R R R R		Register of Deeds Stamp & File Number
4. Lot No, Reco	orded Plat		A B C D E F G H I J K L M
in lines 1 and 2 above were in c	irements of P.A. 74, Michigan conformance with regulations	urvey on <u>September 18, 19 96</u> P.A. of 1970, the corner points mentioned and rules therefore as required in the contribution of the Interior, Bureau of Land	6 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

Description of original monument and accessories and/or subsequent restoration:

1837 Post by John Milny

1971

1980 1980

1980

1993

1994

Post by John Milny
LCRC by W.B. Ruddell. Recorded P
105. Found triangular stone. Raised with 1/2" pipe
LCRC by W.B. Ruddell. Recorded P
620. Found iron in mon box
LCRC by W.B. Ruddell. Recorded P
632. Found iron in mon box
LCRC by T.J. Mueller. Recorded P
637. Found 1/2" pipe in mon box
LCRC by W.B. Ruddell. Recorded P
1233. Found 1/2" pipe in mon box
Per Isabella County Road Commission Plans: Job No. 35564A: Federal Project
by -- Ruddell: L 1 P 44; L 3 P
1.S. Fokens: L 5 P 184 Surveys by L 4 P 460.

Description of corner evidence found and/or method applied in restoring or reestablishing

Found 1/2" pipe in mon box Verified by LCRC P 637 Sept 1996 NW 27.2 Centerline South end 15" CMP

Centerline South end 15" CMP SW 40.4

Centerline South end 15" CMP 23.72

Nov 1996 Witnessed and removed corner. Augered down through mon box at 2.5'. Hit stone.
Unable to determine size - State Highway plans (Job No. 00519) say triangular stone 14"
long. Unable to auger past. Refilled and reset corner.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A standard remonumentation corner was set/stamped with corners code number (K-6) and P.S. 41917 in monument box and is accepted as the best available evidence of the position of the original corner.

WITNESSES:

N85W 103.16' 12" tree (County Road Plans "94")

159.89' N21W Power pole

147.77 N16E

Telephone pole Centerline of South End of 15" CMP Centerline of South End of 15" CMP 27.20 NW SW

40.40' F

23.72' Centerline of South End of 15" CMP Chisel mark in top of 12" CMP WSW

Nail & Cap in South End of Fence Post PK Nail & Disk in Wood Headwall 40.16' NE

Signed by

Date

PROFESSIONAL. SURVEYOR No. 41917

RONALD

R. HARRIS

Surveyor's Michigan License No.