LAND CORNER RECORDATION CERTIFICATE

For corners in		Filing Requirement of Act 74, Mich. P.A. 1	970	
, 0.	Jackson	Located In: Corner Code ##		
1.	(County) Public Land St	10 111 7 10	APPROVE	ON COUNTY D LAND CORNER 345 of 1990
2.	Property Contr	T R	Chairman _. Date	Ocz 13, 1999
3.	in Section Miscellaneous Property in Se	· · · · · · · · · · · · · · · · · · ·		eeds Stamp & File Number
4	Lot No	, Recorded Plat		
			2 5 6 1	D D E F G H I J K L I
do lin la cur Mar abo Cou	hereby certify that ines 1 and 2 abourent manual of su nagement or by a cover were in confor	ppelman in a field survey on September 01, 19, 94 tunder requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned we were in conformance with regulations and rules therefore as required in the trivey instructions of the United States Department of the Interior, Bureau of Land decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 mance with the rules of the Michigan Board of Land Surveyors or by a Decree of a blished, re-established, monumented, re-monumented, recovered, found as	6 18 7 8 19 9 10 30	- 8 - 9 - 10 - 11 - 12 - 13 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 13 - 14 - 15 - 14 - 1
NO	TE: Not more on this ce	than 4 corners, all in the same town and range, may be recorded ertificate.	12 31	32 33 34 35 36
A.				
	JOSEPH WAMPLER 1824	POST SET IN ORIGINAL GOVERNMENT SURVEY ELM 10, N67°W, 32 LINKS = 21.1'W. OAK 9, N30°E, 57 LINKS = 37.6'		ONUMENTATION NER RENONUMENTATION
	H.F. BEAN 1885	FOUND STAKE HOLE, ONE WITNESS, BLACKMAN POST STAND HICKORY 3, S73°W, 23 LINKS = 15.2' SASSAFRAS 2, N57°W, 2½ LINKS = 1.65'	DING	
		CONTINUED ON BACK		
В.	Description of corner evidence found and/or method applied in restoring or reestablishing corner: \$TATE OF MICHIGAN			
		FOUND FIRECLAY WITH 3/4" PIPE (CAP #7863) BOTH BEAN WITNESSES STILL STANDING		JACKSON COUNTY RECORDED
	RONALD ENGER	WITNESSES FROM L.C.R.C., L. 4, P. 131 SPIKE IN 18" HICKORY, S73°W, 15.73'		27 DEC 94 12:12 P.M.
	1988	SPIKE IN 36" SASSAFRAS, S85°W, 1.70' NAIL & CAP IN 6" CHERRY, S40°E, 8.2' (DID NOT FIRECLAY AND 3/4" PIPE AT I-1, T2S, R1W, EAST, 2	FIND NAIL)	GERALD J. MCDEVITT REGISTER OF DEELG
		THE FIRECLAY WAS ACCEPTED AS A PERPETUATION OF THE THE ORIGINAL CORNER AS REMONUMENTED IN 1885. SET JACKSON COUNTY REMONUMENTATION MONUMENT.)F
C.	Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
		$4^{\prime\prime}$ x 36 $^{\prime\prime}$ MON. WITH JACKSON COUNTY REMONUMENTATION BURIED FIRECLAY AND 3/4 $^{\prime\prime}$ PIPE ON NORTH SIDE		
			'3°W 15.73' '5°W 1.70'	
		60d NAIL IN W. SIDE 12" SASSAFRAS STUMP S1	0°W 8.94'	ALANI P
		20d NAIL & RAISED SHINER IN W. SIDE 6" CHERRY S3	55°E 16.36' :0°E 8.07' :ST 29.75'	PROFESSIONAL *
7:	and by	12 1 10/2 D 200 10/	03/94	35998 SET THE STATE OF THE STAT

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

10/03/94

Date ..

Bigned by

Surveyor's Michigan License No.

35998

A: RONALD ENGER 1988

WITNESSES FROM L.C.R.C., L. 4, P. 131
SPIKE IN 18" HICKORY, S73°W, 16.7'
SPIKE IN 36" SASSAFRAS, S85°W, 1.75'
NAIL & CAP IN 6" CHERRY, S40°E, 8.2'
FIRECLAY AND 3/4" PIPE AT I-1, T2S, R1W, EAST, 29.6'