Survey & REMONUMENTATION WEST 1/4 CORNER SECTION 6 TOMPKINS TOWNSHIP LAND CORNER RECORDATION CERTIFICATE MAR 1 8 2000 Filing Requirement of Act 74, Mich. P.A. 1970 For corners in SECTION Comer Code # Located in: JACKSON T 15 R 2W A-2 1. Public Land Survey 2138089 Page: 1 of 1 11/24/1889 02:42F R 2. Property Controlling L-1618 P-28 in Section 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. \_, Recorded Plat 4. Lot No. 5. Private Claims I.RONALD L ENGER, in a field survey on APRIL 2, 19.99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded 10 on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1. POST NOT SET IN ORIGINAL SURVEY. 2. GLO NOTES FOR M-2, T1S,R3W, STATE ORIGINAL POST SET BY JOSEPH WAMPLER, D.S. IN JANUARY, 1824: TAM, 9", S28W, 5; B.O., 11", N40 1/2W 36 1/2 3. IN MAY 1886 JOHN HOLCROFT REPORTED: "FOUND STAKE SET BY CROUL WHEN COUNTY SURVEYOR, WITH BRICK AROUND IT 103 LKS (68.0") SOUTH OF SPRINGPORT 1/4 POST. SET FIRECLAY POST AND TALL STAKE ALONG SIDE OF IT SO AS TO EASIL)" FIND IT." HE RECORDED TWO WITNESSES AS: 34 1/2 (22.8") TAMARACK 6 N2°E S66 1/4°W 13 1/2 (8.9) MAPLE 6 4. CONSUMERS POWER COMPANY DRAWING SHOWS THE CORNER AS A COMPUTED LOCATION. NO MENTION OF MONUMENT AT THE CORNER OR ANY WITNESSES.

B. Description of comer evidence found and/or method applied in restoring or reestablishing comer:

SEARCHED IN GENERAL LOCATION OF CORNER ALONG REMNANTS OF NORTH-SOUTH FENCE. AFTER MUCH SEARCHING, FCUND DEARCHED IN GENERAL LOCATION OF CORNER ALONG REMINANTS OF MORTH-SOUTH FENCE; POSITION FALLS ON MINUTE REMNANTS OF FENCE COMING FROM THE WEST. TRACED REMNANTS TO NORTH-SOUTH FENCE; POSITION FALLS ON MINUTE REMNANTS OF FENCE COMING FROM THE WEST. TRACED REMNANTS TO NORTH-SOUTH FENCE; POSITION FALLS ON EXTREMELY LARGE STONE. TAPED 68.0 FEET SOUTH FROM THIS POSITION INTO SWAMP, FOUND FIRECLAY POST 0.2 FEET ABOVE WATER SURFACE AND SURROUNDED BY STONES. ACCEPTED FIRECLAY AS CORNER PERPETUATED BY HOLCROFT. SET 4" X 36" CONCRETE MONUMENT WITH JACKSON COUNTY ALUMINUM CAP IN PLACE OF FIRECLAY. LEFT FIRECLAY ON NORTH SIDE OF CONCRETE MONUMENT.

C. Description of monument for comer and accessories established to perpetuate locating the position of the comer:

C. Description of monument for curies and accessories		OF MICH
A-2 T1S R2W  4" X 36" CONCRETE MONUMENT AND JACKSON COUNTY CONCRETE MONUMENT AND JACKSON COUNTY CONCRETE MONUMENT AND JACKSON COUNTY CONCRETE MONUMENT M-2 T1S, R3W SURVEY MARKER SIGN POST  AZ. 140"  NAZ. 140"  NAZ. 196"  NAZ. 300"  NAZ. 304"  NAZ. 00"  NAZ. 00"	19.79' 38.65'	RONALD L.  ENGER PROFESSIONAL SURVEYOR NO. 28409
Signed by R-ld LEX	Date <u>APRIL 14, 1999</u>	AOFESSIONAL MARIE
Surveyor's Michigan License No. 28409		TE ROMEO OF PROFESSIONAL SURVEYORS, JAN. 28, 1971

FORM APPROVED BY MECHGAN STATE BOARD OF PROFESSIONAL BLICKEYORS, JAN. 28, 1971 REVISED MAY 14,1975