APPROVED LAND CORNER P.A. 345 of 1990 NE CORNER OF SECT	ION 25 SPRING AF	RBOR TWEISER 1453 PAGE 290
Chairman Mantol utilizend		
Date Dec. 27, 1994 LAND CORNER	R RECORDATION CERT ment of Act 74, Mich. P.	
For corners in Jackson	Hent of Act 74, Mich. P.	A. 1970
(County) Located In:	Corner Code ##	STATE OF MICHIGAN JACKSON COUNTY
1. Public Land Survey T3S R2W	<u>M-9</u>	RECORDED
T R T R	-SURVEY &	19 JAN 95 12:36 P.M.
T R	EMONUMENTATI	ON GERALD J. McDEVITT
in Section S T R	141 (14)	REGISTER OF DEEDS
3. Miscellaneous S T R Property in Sec. S T R	MAY 0 3 1995	Register of Deeds Stamp & File Number
4. Lot No , Recorded Plat	COMMISSION	
5. Private Claims		A B C D E F G H I J K L
		2 3 5 4 3 2 1 3
		4 7 8 9 10 11 12
Arden S. Pierson PS, in a field survey on September do hereby certify that under requirements of P.A. 74, Michigan P.A. of		oned
in lines 1 and 2 above were in conformance with regulations and current manual of survey instructions of the United States Departm	rules therefore as required in	n the
Management or by a decree of a Court of Law and/or that the corner p	points mentioned in lines 3, 4 a	and 5 8 19 20 21 22 23 24
above were in conformance with the rules of the Michigan Board of L Court of Law; established, re-established, monumented, re-mo		
expressed below:		10 30 29 28 27 26 25
NOTE: Not more than 4 corners, all in the same town and on this certificate.	range, may be recorded	11 12 31 32 33 34 35 36
A. Description of original monument and accessories and/o		13
Records show he set a post a 12" Hickory -N48°W- 73 links County Surveyor Records also dated May-June, 1886, that h witnesses: 24" White Oak - 12" Maple -N84°	14" White Oak show in a survo e set a firecla	k -S87°W- 84 links ey by H.F. Bean, y post with ks(138.60')
*(SEE BACK OF SHEET)		\$ 2.00 REMONUMENTATION \$ 9.00 CORNER REMONUMENTATION
B. Description of corner evidence found and/or method ap	plied in restoring or reesta	ablishing corner:
Section 25, Sprin	g Arbor Townshi	<u>p</u>
M-9 - Found pinched pipe 1.5' bel of Road. Excavated 4' x 4' a of the original corner. The faithful perpetuation of the The corner position is 15.84 Section 30 T3S, R1W. Replace County Monument 3" below sur	rea, 3.5 'deep apipe is accepted position of the '+/- North of the distribution of the contract of the contrac	and found no evidence d as a careful and e original corner. he NW corner of with Standard Jackson
		where OF Michigan
C. Description of monument for corner and accessories es	tablished to perpetuate lo	cating the position of the coner:
M-9 (NE corner		* ARDEN S. ** ** PIERSON **
Jackson Coun	ty Monument	PROFESSIONAL 4
(CLOSING CORNER IS SOUTH 1 Witness sign post set -Nor	5.84') th- 30.0'	SURVEYOR No.
Nail & tag #13039 W. side	13" Maple -S20°1	E- 43.98 13039
Nail & tag #13039 S. side Nail & tag #13039 SE side	21" Walnut -N60'	W- 44.91
Nail & tag #13039 SE side Nail & tag #13039 W. side	15 Maple -N05°	W ±0.00
*Standard Jackson Monument is a 1	/2" iron rod 36	" long with a Jackson
County Remonumentation disk enca		crete cylinder. November 1, 1994
Signed by 13039	Date	
Surveyor's Michigan License No. 13039		FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 15

NE CORNER OF SECTION 25, SPRING ARBOR TOWNSHIP

Certification by H.F. Bean (page 620, GLO Notes) "post set are fireclay, three inches in diameter and two feet long"

Jackson County Road Commission Records from 1961, show the following information for M-9:

Iron in North side of road 9" Walnut -N60°W- 45.19' 12" Maple -S45°E- 59.35'

SW corner of house foundation -N10°E- 55.10' Recorded in Liber 1, page 127, by Harold W. Dorcey PS #9429, dated June 12, 1972. "Found iron 15.34' (15.84') feet North of South-West Corner Section 19, T3S, R1W." Did Not Witness

FIELD NOTES BY DORCEY, PS DATED APRIL & MAY ,1972 PROVIDE A SECTION BREAKDOWN BY SURVEY OF SECTION 24, SPRING ARBOR TOWNSHIP.- HE SET EAST 1/4 CORNER OF SECTION 24 BY SINGLE PROPOR-TION MEASUREMENT BETWEEN THE SE CORNER OF SECTION 24 AND THE EAST 1/4 CORNER OF SECTION 13. THE DISTANCE FROM M-9 WEST TO L-8 IS SHOWN AS 2654.05' (MEASURED 2654.04') AND THE DISTANCE FROM M-9 NORTH TO M-8 IS SHOWN AS 2551.87'