LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In:	- '	·		
(County)	Located In Corn	er Code #		
1. Public Land Survey		13	MAR (11.200)	
2. Property Controlling in Section	T <u>26N</u> R <u>6W</u> S T R S T R	-13	SECTION	
Miscellaneous Property in Section	S T R		Register of Deeds Stamp & File Number	
4. Lot No:	Recorded Plat:		ABCDEFGHIJKLM	
5. Private Claims:			2 - 6 - 5 - 4 - 3 - 2 - 1	
requirements of PA 74, Mic and 2 above were in confor the current manual of sun Interior, Bureau of Land Ma corner points mentioned in of the Michigan Board of	ald survey on Sept. 23, 1999 do hereby statishigan PA of 1970, the corner points mention mance with regulations and rules therefore a vey instructions of the United States Departnagement or by a decree of a Court of Law arilines 3, 4 and 5 above were in conformance versions. Land Surveyors or by a Decree of a Commonumented, recovered, found as expressed	ed in lines 1 s required in ment of the id/or that the with the rules out of Law;	3	
NOTE: Not more than 2 corners, all in the same town and range, be recorded on this certificate.		ge, may	10 30 -29 -28 -27 -26 -25 -11 -12 -31 -32 -33 -34 -35 -35	
			13	
A. Description of original monument and accessories and/or subsequent restoration:				
E-1 – GLO – Bervoort & Mullett – 1839 – Set ¼ Post Beech 12" N30 ½°E 19L. Beech 16" N22°W 35LW.S. Merrill –1911- Ran N. line of TWP Fargo Eng – 1912 – Set Iron & crockery – S.PLCRC – L.1, P.210 – C. Roser – 1973 – N¼ Cor. Sec. 4 was erroneously est, by Fargo 1913 and has since been accepted by landowners and used by Private Surveyors to est, center of sec.4. We have accepted Fargo corner as occupied, since the government corner is a lost. At corner fnd. Fargo Pipe, Conc. Mon. & Rerod. Set Cedar gd. Post w/ location tag 4" Balsam S59°E 71.4' 7" Balsam S22°E 76.5' 10" Maple cluster (3) N46°W 103.2' Dirt Rd. Due West 16.5'		Manistee #1 - LCRC - L.2, N20°W 6" T S70°E 4" Ba S30°E 6" Ba S65°W 5" P - Certificate Of (DNR) Fnd. nail in 6 Fnd. nail in 6 Fnd. nail in 6 Fnd. nail in 6	- LCRC – L.2, P.33 – J. Wilcox – 1977- FND. Conc. mon. & 1" pipe N20°W 6" Tri. Maple 6.79' S70°E 4" Balsam 71.47' S30°E 6" Balsam 76.31' S65°W 5" Poplar 32.84' - Certificate Of Survey L.4 P.151–E. Farrier – 1991 – Fnd 1" I.P. (DNR) Fnd. nail in clump (7) 4"-10" Maple N65°E 61.58' Fnd. nail in 9" Balsam S57°E 71.62' Fnd. nail in 9" Balsam S33°E 71.35' Fnd. nail in 9" Balsam S21°E 76.37' Fnd. nail in clump (7) 6" Maple	
B. Description of corner evidence found and/or method applies in restoring or re-establishing corner:				
<u>F-1</u> – Standard ¼ corner common to Section 4, T25N, R6W & Section 33, T26N, R6W- Found 1" Fargo Pipe w/ Conc. Mon. along side- 0.24' SE per LCRC's & Rec. survey. Dug down and found the crockery in place around Fargo's 1"X2.3" long pipe with hooked end. CL of N-S gravel rd. is 16.5'± W. Accepted Fargo's Pipe as the best available evidence of the position of the original corner.				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
F-1- Removed 1" Fargo Pipe & conc. Mon. and replaced with 4" DNR Alum. Cap on 1" X 36" Galv. Iron pipe at Fargo pipe position. Reset 7 FND. piece's of broken crockery at base of Mon. as memorial. Set blue carsonite post 1'N N20°W 6.52' to set N&T in E side 15" R. Maple clp6 (JW) N58°E 61.59' to set N&T in SW side 15" R. Maple clp8 (EF) S63°E 71.54' to set N&T in SW side 13" B. Fir (CFR,EF,JW) S37°E 71.33' to set N&T in SW side 12" B. Fir (CFR,JW,EF) No. S26°E 76.32' to set N&T in W side 12" B. Fir (CFR,JW,EF) N51°W 103.05' to set N&T in NE side 16" R. Maple clp3 (CFR)				
Signed by:	ing W. Ma War	Date:	12/9/1999	
Surveyor's Michigan License No.: 39088				
Ratified by Peer Group				

3019504 Page: 1 of 1 12/23/1999 11:04A REMON LB: 8 PG: 50