## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970

For Corners In: Kalkaska (County)	Located In	Corner Code #	
1. Public Land Survey	T 26N R 5W	<u> </u>	
Property Controlling in Section	S T R		
Miscellaneous     Property in Section	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No:	Recorded Plat:		ABCDEFGHIJKIM
5. Private Claims:			1
requirements of PA 74, Mi and 2 above were in conforthe current manual of su Interior, Bureau of Land Ma	ield survey on August 30, 2010 do chigan PA of 1970, the corner point ormance with regulations and rules evey instructions of the United Statement or by a decree of a Coullines 3, 4 and 5 above were in con-	ts mentioned in lines 1 therefore as required in tes Department of the t of Law and/or that the	3 4

1	A E	3 0		E	F		3 H	1 1	J		( L	М
•	İ.		ļ									
2	Γ'	 	٣i	$\neg$	_ 1		3 I	-	— 2 І	-	<u></u>	
3	Н		Н	_	$\dashv$		$\dashv$	—	$\vdash$		H	-
4	<del> -</del> :	<del>-</del>	ا ا	-	\$	-	1	þ	-1	ı—	-1	2
5	<u> </u>	_		_				_	_			
6	_1	! 8—	_1	7_	—1	6—	1	5—	—1	4—	L_1	3—
7	<u> </u>	_									Ш	Щ
8	_1	! 9—	-2	<b>.</b>	<u>2</u>	1—	<u>2</u>	2	<u>2</u>	] 3——	2	4—
9	<u> </u>	_	Н						Н			Щ
10	<b>├</b> -3	ļ	<u>2</u>	-	—-2	8	<u>2</u>	 7—-	<u>2</u>	6	2	5
11	$\vdash$	$\vdash$	-					Ц				Н
12	<b>├</b> -3	! !1—	—3	2—	—з	3—	—3	 4	—з	5—	-3	6
13		Ц.	Ш									L_

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

- A. Description of original monument and accessories and/or subsequent restoration:
- <u>I-11</u> **1852** GLO G. Cannon Set post corner of sec. 26, 27, 34 & 35,
  - 1) Y Pine 18" N51°E 118
  - 2) Y. Pine 20" S46°W (omitted)
  - 1956 DNR corner record B. D. Buckler, PS #8887 This corner was found by forestry division survey crew while making a partial resurvey of this township. Probable original corner with both stumps in place, but burned. The stumps of the old corner, which was 75 links North and 240 links East are in place, but the NE stump bears N25W instead of N25E. This stump has what appears to be a partial face and notch. - Set 1" pipe with 4" brass cap, 3) 8" W. Oak S42°E 39 L. 4) 7" W. Oak N31°E 52L.
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- 1-11 Corner common to sections 26, 27 34, & 35, T26N, R5W Found 4" Department of Conservation Brass Cap Monument on 1" iron pipe. Found witness #3 in good condition and stump remains of witness #4. Measured S51°W 35.5' to 18" YPS - Apparent witness #2 and N55°E 76' to Face 24" Pine Stp. for apparent Witness #1. 4" DOC Monument accepted as a careful and faithful perpetuation of the position of the original corner.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- 1-11 4" DOC Brass Cap on 1" iron pipe. Set Blue carsonite Post 1' North.

S85°E 24.36' to set nail & tag at fd. nail in S side 5" R. Pine S42°E 25.89' to set nail & tag in SW side 14" W. Oak (#3) S05°E 15.59' to set nail & tag at fd. nail in W side 10" W. Oak S62°W 5.09' to set nail & tag in N side 6" W. Oak N19°W 37.08' to set nail & tag at fd. nail in E side 8" W. Oak

OF MICHIGA CRAIG W. **McVEAN** ROFESSIONA No. 39088 POFESSION

Surveyor's Michigan License No.:

39088

Date: