LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. PA 1970


4. Lot No:	Miscellaneous Property in Section	2. Property Controlling in Section	1. Public Land Survey	For Corners In: Kalkaska (County)
Recorded Plat:	S S S	, G	T 27N R 8W	Located In
			E6	Corner Code #

I, <u>Craig W. McVean</u>, in a field survey on <u>July 8</u>, 2003 do hereby state that under requirements of PA 74, Michigan PA of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Private Claims:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Register of Deeds Stamp & File Number



A. D.

GLO -- L. Lyon -1850 - Set Bee Sugar 16" N34°W 10 L., Heml CSR -- FB #39 -- E.B. Dennis --

- Sugar 16" N34"W 10 L., Hemlock 18" S66°W 21 L.

 CSR FB #39 E.B. Dennis 1895 Set new 1/4 south at proportional distance between Meander South and Sec. Corner NW of Sec. 16 or 39.47 1/2 CH. South of said corner. Maple 12" N49 1/2° W 6 3/4, Maple 16" N72°E 39

 CSR Lg. Bk. P. 34 and FB. 25, p. 105 W. S. Merrill 1903 shows corner and distances S & E.

 CSR FB. 7, p. 49 & 50 Shows corner & Distances

 DNR Cor. Rec. Ken J. Ostling 1967 Set 1" pipe with 4"

 Aluminum cap by proportional measure between section corner north and meander corner south according to record survey by E.B Dennis of 1895 in which he recovered original

- Description of original monument and accessories and/or subsequent restoration:

 GLO L. Lyon -1850 Set Beech ¼ Post

 MC and Sec. Cor. and reestablished this corner by proportional measurement. Could not find any monument, probably

- destroyed by road construction.
 6" Cherry N74°E 56.6', 5" Red Oak S75°E 61.0'
 Recorded Survey L. 2, p. 853 E. Farrier 1984
 Fd. DNR Monument 2' west of centerline N-S rd.
 N70°E 56.65' 10" twin Black Cherry
 S78°E 61.22' 11" Oak
 S53°W 48.82' 3" twin Oak
 LCRC L. 2, p. 395 E. Farrier 1989
 Fd. DNR monument 2' ± west of centerline N-S gravel Rd.
 S62°W 48.27' 4" Twin Oak; S75°E 61.16' to 10" Oak;
 N78°E 56.63' twin 10" Cherry; N60°W 84.45' 10" White Pine
- B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:
- <u> 6</u> 14 corner common to Sections 16 & 17, T27N, R8W - Found 4" DOC Aluminum cap, 1.5' ± West of centerline N-S Dockery (gravel) Rd. at centerline of Trail 55 east and 19' south of Trail 55 west per Ostling & Farrier. DOC(DNR) Monument accepted as a careful and faithful reestablishment of the position of the original corner.

OF MICHICA

<u>同</u>こ

Description of monument for corner and accessories established to perpetuate locating the position of the 2 — Found 4" DOC Aluminum Cap — buried in road.

N74°W 31.77' to found nail in North side 10" White Pine

N42°E 76.81' to found nail in Southeast side 8" Cherry

S76°E 50.48' to found nail in North side 10" Sugar Maple Clp.

S56°W 48.71' to found nail in Southeast side twin 10" Red Oak (EF)

S78°E 61.35' to set nail and tag in South side 16" Oak (KJO,EF)

Set Blue Carsonite Post with Location tag 33' West

Surveyor's Michigan License No.: Signed by: ma

39088

Date:

CAENADIT

39088

SURVEYOR R

ROFESSIONAL SURVEYOR

MCVEAN

POFESSIONAL

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS JAN. 28, 1971 Revised May 14, 1975 Revised Jan. 1983 Revised Oct. 1995