

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Keweenaw (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S 34 T 56N R 31W _____ S 34 T 56N R 31W _____ S _____ T _____ R _____	8 4
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat _____		
5. Private Claims _____		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 09/12/13 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(8-Sec. 34) Center-West 1/16 corner, Section 34. Not previously monumented.

(4-Sec. 34) Northwest 1/16 corner, Section 34. Not previously monumented.



B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(8-Sec. 34) Established the position for the corner midway and on a straight line between 1/4 corner
1310.90' west and Center of Section 1310.90' east.

(4-Sec. 34) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(8) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
3" Tamarack N85°W 10.05' mrkd "1/16S BT"
3" Tamarack N08°E 21.75' do
6" Cedar N52°E 42.45' do
5" Tamarack S02°E 23.05' do
Set sq'd cedar post adjacent.
E= 7906810.647 N= 270137.492

(4) Set 1"IDx32" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
3" Tamarack N26°W 24.5' mrkd "1/16S BT"
6" Tamarack N64°E 21.8' do
3" B.Spruce S35°E 27.8' do
4" Tamarack S43°W 3.35' do
Set sq'd cedar post adjacent.
E= 7906808.430 N= 270536.076

Bearings are magnetic. Coordinates are MCS83 in meters (NAD83(2011) Datum).
Coord. Ref.=USACE monument "RAMP 1995": N= 268244.768 m. E= 7906171.601 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 10/02/2013

For the Michigan Department of Natural Resources, Forest Resources Division