

SURVEY & REMONUMENTATION

MAR 19 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

Keweenaw

(County)

Located In:

Corner Code #

1. Public Land Survey T 58 R 29
T 58 R 29
T _____ R _____
T _____ R _____
2. Property Controlling S _____ T _____ R _____
in Section S _____ T _____ R _____
3. Miscellaneous S _____ T _____ R _____
Property in Sec. S _____ T _____ R _____

G - 2/3 (2)
G - 4/5 (4)

REGISTER'S OFFICE

County of Keweenaw } SS

Received for Record, the 9th
day of December A.D. 1996
at 1:00 o'clock P.M., and Recorded
in Liber 1 of LCR
on page 153
Robert Rosenberg, Dep.
Register of Deeds

Register of Deeds Stamp & File Number

1. Lot No. _____, Recorded Plat _____
5. Private Claims _____

I, John I. Haataja, in a field survey on September 19, 1996,
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the
current manual of survey instructions of the United States Department of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented, recovered, found as
expressed below:

**NOTE: Not more than 4 corners, all in the same town and range, may be recorded
on this certificate.**

A. Description of original monument and accessories and/or subsequent restoration:


G - 2/3 Meander cor. between 3 & 4.
Wood Post
Cedar 10" N 30 E 17 lks.
Birch 8" N 20 W 9 lks.

G - 4/5 Meander corner between 9 & 10.
Wood Post
White Pine 10" S 15 E 23 lks.
White Pine 16" S 28 W 17 lks.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G - 2/3 No evidence of original cor. FND.
Re-established corner by extend-
ing line from NW cor. of Sec. 3
South through the 1/4 cor. to high
water mark.

G - 4/5 No evidence of original cor. FND.
Re-established during survey of
Assessor's Plat of Lake Medora.



Ratified by Peer Group
In accordance with P.A. 345
Co. Rep. James M. Hubert
Date 12/6/96

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G - 2/3 Meander corner between 3 & 4.
1" pipe with brass cap
18" W. Pine N 6 W 18.56'
5" Maple N 56 E 16.17'
7" Cedar N 83 E 30.22'
4" Cedar S 54 E 38.79'
2' South to waters edge

G - 4/5 Meander cor. between 9 & 10.
Grouted brass cap in rock face.
N.E. corner lowest conc. dock
step N 80 W 31.13'
6" Cedar S 83 E 30.61'
6" Cedar S 20 E 4.41'
28" W. Pine S 33 W 24.63'
5' N. to waters edge

igned by John I. Haataja
urveyor's Michigan License No. 19833

Date 11/27/96