

SURVEY & REMONUMENTATION

APR 27 1995

COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN
COUNTY OF KALAMAZOO
RECEIVED FOR RECORD
95 JAN 5 AM 9 46

For corners in

Kalamazoo

(County)

Located In:

Corner Code #

Cooper Township

1. Public Land Survey

T 1 S R 11 W

E-4

T R

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

James J. Jones
CLERK-REGISTER

LIBER

1 PG 1250

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat

5. Private Claims

I, Robert E. Snell, in a field survey on May 6, 19 94,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

1826: U.S. Government Survey; Set 1/4 Section Post.

Hickory 12" South 25° West 10 Lks

Beech 14" North 58° East 6 Lks

1870: F. Hodgman, County Surveyor; Quarter Section Corner. Found original stake hole in road. Planted stake and brick.

Maple 8" South 80° West 41½ Lks

Maple 10" North 15° East 86½ Lks

1921: Kalamazoo County Road Commission; East 1/4 Post Section 8, Stone.

Hickory 8" N 75° E 27.2' Maple S 80° W 27.4' Fence East and West on Line 27'

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: North of iron rod at Sta. 79+20.6

1944: Wilkins and Wheaton Engineering Company; Found iron.

1971: D. Ratekin, Surveyor; LCRC, Liber 1, Page 7, Found 1/2" iron 0.4' below pavement.

1978: Al McMachen, Surveyor; LCRC, Liber 1, Page 721, Found iron.

1994: Found iron (1/2" x 20") in Centerline of Road. Dug a hole (7' x 4'). Found no other evidence. Ran the East Line of Section 8. Measurement to the Northeast Corner (ratified July 21, 1994) was 2643.37'. Measurement to the Southeast Corner (Not ratified, LCRC, Liber 1, Page 185) was 2646.36' and the angle from the Northeast Corner to the Southeast Corner (angle right) was 180°-00'-27".

7-21-94

RATIFIED

BY KALAMAZOO COUNTY
REMONUMENTATION

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-4 East 1/4 Post Section 8, T. 1 S., R. 11 W., Ratified by the Kalamazoo County Remonumentation Program Peer Group on July 21, 1994. Found iron as shown on 1944 survey by Wilkins and Wheaton Engineering Company, 1971 LCRC and 1978 LCRC and is accepted as a careful and faithful perpetuation of the position of the original corner. Placed a 20" Harrison monument in place of iron with a monument box over.

Exist. Nail in North Side Telephone Pole East 28.05'

Nail in Northeast Root 24" Maple North 48° West 41.53'

Nail in Southeast Side 34" Maple West 64.16'

Nail in East Side 15" Elm South 22° West 44.63'

Signed by *Robert E. Snell* Date 1-3-95

Surveyor's Michigan License No. 9734