



LC-000097
Page: 1 of 1
12/20/1999 10:07A
BK-2 Pg-350

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in COMSTOCK TWP
KALAMAZOO
(County)

Located In: Corner Code #

1. Public Land Survey T 2S. R 10W. E-1
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

SURVEY &
REMONUMENTATION

FEB 08 2000

SECTION

Register of Deeds Stamp & File Number

4. Lot No. , Recorded Plat
5. Private Claims
6. IWM Job No. 32282

I, Allen H. McMachen, in a field survey on November, 19 99 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:

- 1827 - Robert Clark Jr., D.S., Intersected North boundary 180 lks. East of post. Set post at intersection corner to Sections 4 and 5, Wh. Oak 12" S. 12 1/2° W. 45 lks., Wh. Oak 11" S. 79° E. 52 lks.
1885 - F. Hodgman, C.S., "Found stake and stone N. 12 1/2° E. 45 lks from stump of bearing tree U.S. set post. Bearing trees of resurvey standing.
1894 - Ed Strong, C.S., "Tile found".

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found iron in monument box. Removed iron (6 1/2" long) and found broken top section of tile 2.5 feet below grade. Removed broken tile and found bottom section of tile in good condition 3.2 feet below grade. Bottom section of tile was directly below position of surface iron. Measured West 118.85 feet (G.L.O. = 118.80 feet) to a found stone (ratified) at the Southwest corner of Section 33, Richland Township.

RATIFIED
BY KALAMAZOO COUNTY
REMONUMENTATION
PEER GROUP
11-18-1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found clay tile is accepted as a careful and faithful perpetuation of the position of the original corner. Placed a 20" Harrison Monument over bottom section of tile with a monument box over.
Accessories:

- Mag nail in East side of fence post N. 55° E. 62.02'
Nail & Tab (existing) in West side of U. pole S. 35° E. 41.18'
Nail in East side of 8" Hickory S. 30° W. 65.16'
Nail in East side of 4" Maple N. 10° W. 65.08'
IWM capped iron North 18.07'



Signed by Allen H. McMachen
Surveyor's Michigan License No. 16935

Date 12/17/99