	REMONUMENTATIO	n O					
1	7 FEB 0 8 1999		LIBER	2ragé 38	(00L RE *98	C>
Fo	TATALAZOO	LAND CORNER F TWiling Requirement			CLERK-RE	DEC 15	
1.		T <u>4S.</u> R <u>11W.</u> T R T R T R	M-10	- 1	EGISTER	ALAMAZOO DR RECORD PM 3 50	MICHIGAN
	Property Controlling S in Section S Miscellaneous S	T R T R T R T R		_	gister of Deeds Sta	·	
	Lot No, Recorded Platerivate Claims				- A B C D E	F G H J	K_L
l, do in li ma Ma 5 a Dec	I, Allen H. McMachen, in a field survey on November 5, 19, 96 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Professional Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded					-9 -10 -11 -16 -15 -14 -21 -22 -23 -28 -27 -26	12-13-13-
_	on this certificate.				12 -31 -32	33 34 35	36-
A.	Description of original monument a 1826 - Robert Clark Jr., D.S., Set post, 1899 - F. Hodgman, C.S., "Found store beside Maple 5" N. 421/2° E. 78 I 1949 - Wilkins & Wheaton, "Tile" Me	quarter Section cor., T ne of former survey 291 ks., D.O. 6" S. 62½° E. 5	am 12" N. 82½° W. 1 ½ lks. North of ½ cor 59 lks	10 lks., Tam 7" : ner, Section 30,	S. 20° W. 54 lks Brady Twp., Set po	ost with	
B.	Description of corner evidence fou	nd and/or method app	plied in restoring or	reestablishing	comer:		
	No corner marker found due to exte and halfway between the NE cor., See	nsive road work in are c. 25 (iron in box) and t	ea for bridge. Placed the SE cor., Sec. 25 (½	Harrison Mon 2 mile = 2655,33	ument in mon. box 9).	on line	
	<i>š</i> .			BY KALA REMO	RATIFIED MAZOO CO NUMENTATI ER GROUP 2-19-1948	UNTY	
C.	Description of monument for corne	er and accessories est	ablished to perpetu	ate locating the	e position of the co	emer:	
1	Harrison Monument placed reestablishment of the position of	per above description of the original corner. Acc	is accepted as a careful cessories:	and faithful	White the same	F M I CH	
	Nail & Tab (5' high) in U. Pole Nail & Tab (3' high) in 10" Ash I Nail & Tab (4' high) in 12" Mapl Nail & Tab (4' high) in 14" Elm I	N. 80° E. 59.11′ e S. 75° W. 47.24′	4		McI PRO	LEN H. MACHEN FESSIONAL JEVEYOR NO. 6935 ES SIONAL SERVICE FESSIONAL	WHAT THE THE THE THE THE THE THE THE THE TH
	600 H n	1cM.		12 /	SED PROF	ESSIONAL SOUNANT	

Signed by_

Surveyor's Michigan License No.

IAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983