

NOV 21 1997

COMMISSION

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

RECORDED
LAKE COUNTY, MI.

LIBER 004 PAGE 0031

SEP 12 10 30 AM '97

James H. Decker

REGISTER OF DEEDS

For corners in

Lake _____ Located In: _____ Corner Code # _____
(County)

- | | | | | | |
|------------------------------------|---|-----|---|-----|-----|
| 1. Public Land Survey | T | 17N | R | 11W | H-5 |
| | T | | R | | |
| | T | | R | | |
| | T | | R | | |
| 2. Property Controlling in Section | S | T | R | | |
| | S | T | R | | |
| 3. Miscellaneous | S | T | R | | |
| Property in Sec. | S | T | R | | |

Register of Deeds Stamp & File Number

4. Lot No. _____ Recorded Plat _____
5. Private Claims _____

Robert L. Wetherell April 2, 1997

I, _____, in a field survey on _____, 19____, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-5 - 1/4 Corner Common to Sections 10 and 15, T17N, R11W, Lake Co., Mi.

1838 - John Hodgson, G.L.O.	1983 - R. Wetherell, LS 24624	1983 - C. Cole, LS 17615	1996 - R. Wetherell, LS 24624
#1 - 14" Beech N9°E 37'	Set 1/2" re-bar in centerline of	L.C.R.C. - L. 03, Pg. 001	Survey recorded L. 004, pg. 13
#2 - 7" Beech S43°E .31'	road East and West and in line	Same accessories as	Same as accessories as
	with fences North and South.	Wetherell's	Wetherell's
	#3 - P.Pole S2°W 70.97'	1990 - R. Wetherell, LS 24624	
	#4 - 8" Cherry N11°E 33.25'	Survey recorded L. 003, Pg. 245	
	#5 - 6" Cherry N37°E 58.90'	Same accessories as	
	Survey recorded L. 02, Pg. 441.	Wetherell's	

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-5 - 1/4 Corner Common to Sections 10 and 15, T17N, R11W, Lake Co., Mi.

I found the 1/2" re-bar as established in 1983.

Condition of the accessories are as follows: #1 gone, #2 Gone, #3 Found in good condition, #4 Found in good condition, #5 Found in good condition.

CERTIFIED BY THE LAKE CO. PEER REVIEW GROUP
IN ACCORDANCE WITH P.A. 345
CHAIRMAN *R.L.W.*
DATE *8-27-97*

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-5 - 1/4 Corner Common to Sections 10 and 15, T17N, R11W, Lake Co., Mi.

I replaced the 1/2" re-bar with a 3/4" x 24" re-bar and Lake County Brass Cap, and is accepted as a careful and faithful re-establishment of the position of the original corner.

- 8" Elm S75°E 152.14' (60d spike in N. side)
16" Forked Cherry N11°E 33.20' (60d spike in W. side) #4
10" Cherry N55°E 51.75' (60d spike in N.W. side)
P.Pole S6°W 70.93' (Consumers Power Tag in E. side)

Witnessed by *Robert L. Wetherell*
24624

Date *8-27-97*

Surveyor's Michigan License No. _____

