LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. PA 1970

	Filling Reduitement o	ACCT 4, WICH, TA 1070	PECEIVED 05/05/2014 3:55:21 PM
For Corners In:	t another line Corner	Code #	05/05/2014 3:55:21 PM LAKE COUNTY, MICHIGAN SHELLY MYERS, CLERK/REGISTER/CFC
Lake (County)	Located In Corner		RECORDED 05/05/2014 3:56:18 PM LAKE COUNTY, MI DEFENSE
	T 20N R 11W F13	LAKE COUNTY FOR	SHELLY MYERS, REGISTER OF DEEDS
Public Land Survey	T R		RECEIPT# 5785, STATION 1 \$14.00 LAND CORNER
2. Property Controlling	s T R		
in Section	s T R		Liber $\mathbb{C}8$ Page 1
3. Miscellaneous	s T R		Tayo 1
Property in Section	s T R	Regi	ster of Deeds Stamp & File Number
4 L (N).			
4. Lot No:	Recorded Plat:	1 A B C	DEFGHIJKLM
5. Private Claims: _		2 - 6	- 5 1 - 1 - 1 - 1
L Joshua R Davidson in :	a field survey on November 13, 2013 do hereby	state that	
under requirements of PA	74, Michigan PA of 1970, the corner points me	entioned in	-8 9 10 11 12
required in the current mar	e in conformance with regulations and rules the nual of survey instructions of the United States D	Department 1	
that the corner points men	and Management or by a decree of a Court of I tioned in lines 3, 4 and 5 above were in conform	nance with 7	
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:			-20
		9	
NOTE: Not more than be recorded on this ce	2 corners, all in the same town and rang ertificate.	1	27 - 26 - 25 - 25 - 27 - 26 - 25 - 25 - 25 - 25 - 25 - 25 - 25
		11 12 -31	32 33 34 35 36
		13	
A. De a significant de significant construction and for subsequent restauration:			
A. Description of original monument and accessories and/or subsequent restoration:			
F13 – 1837 – GLO Survey – J. Hodgson – South Boundary – ¼ Post in Stream. - 1931 – CSR, Field Notes & Survey, South from ¼ post common to Sec. 4 & Sec. 33 – G. H. Johnson, PS #504 – No corner description or witnesses.			
fieldbook. 1) Beech 10" S62½°E 26; 2) Beech 7" S60°W 36 - 1977 – LCRC L. 2, P. 307 – Clint Cole, PS #17615 – F1, T19N, R11W – Fd. 1" Iron Pipe; 8) 4" W. Pine S37°W 35.17';			
-19?? - CSR - G. H. Johnson, PS #504 - 3) Beech 10" 9) 12" Che N85°30'E 165 lks.; 4) Beech 24" N53°E 8 lks.; 5) Beech 8"			27 ['] ; 10) 8" Ironwood S29°E 51.40'
N85°30°E 165 iks. N31°W 29 lks.	; 4) Beech 24 No3 E 8 iks.; 5) Beech 8	- 1982 - LCRC, L.3, P.27	– C. F. Roser, PS #12028 – F1, T19N,
4020 CSD Field N	otos i Suniov C. H. Johnson DS #504		fits 3 RLS, Clint Cole wits; pipe is at old n. cor. N & W is East, 116'±. Added
- From ¼ on Twp. Line West to river 277'. From Above ¼ ced. post w/ loc tag. 9) 13" B. Cherry N25°E 11.32';			3" B. Cherry N25°E 11.32';
post East to river 42 S31°45'W 74.5'	25'. 6) Elm 6" S51°15'E 56'; 7) Elm 6"	10) 8" Horn Beam S30°E 11) N. edge Pine River D	51.40'; 8) 6" W. Pine S35°W 35.15' Due South 94'+
11) W. sage / me (Wish bus docume) _			
B. Description of corner evidence found and/or method applied in restoring or re-establishing corner:			
F13 – Standard ¼ corner common to Section 33, T20N, R11W – Found 1" iron pipe with stones around pipe and cedar post with location tag. Found witnesses #8, #9(dead), #10, & #11 fitting position per the 1977 and 1986 corner			
record. Pipe has been used as a common corner by Johnson, Cole and Roser. Pipe is located 86'± North and			
270'± East of Pine river. Position of found 1" iron pipe accepted as the best available evidence of the position of the original corner.			
and and agreement			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:			
F13 - Added a stamped 4" DNR aluminum cap to found 1" pipe Set blue post with location tag 1' North.			
N85°E 25.75' to set nail & tag in S. side twin 12" & 16" R. Maple			
S86°53'E 42.76' to 4" DNR aluminum cap on 1" pipe (N¼ corner section 4, T19N, R11W)			
S26°E 51.42' to found nail in W. side 10" Ironwood (#10)			
S37°W 35.08' to set nail & tag in SE. side 22" W. Pine (#8)			
Cinned by	$I \cap D I$	D-t-	
Signed by:	- 1h. North	Date:	5, 2014
Surveyor's Michigan	License No.: 46659	<i></i>	