## SURVEY & REMONUMENTATION

APR 28 1995

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE	OF MI	CHIGAN
COUNTY	OF LE FO FOI	ELANAU RECORD

1994 DEC 12 PN 1: 42

Barker	هـ	Kir	Ł
REGISTER	OF	DEEDS	

For corners in		,	Barbara Kirt
LeeLanau (County)	Located In:	Comer Code ##	REGISTER OF DEEDS
Public Land Survey	T <u>32N</u> R <u>11W</u> T R	G-12	<i>‡</i> 370
	T R		LIBER 2 PAGE 67
2. Property Controlling in Section	S T R S T R	1	
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No	, Recorded Plat		A B C D E F G H 1 J K L
5. Private Claims			2 6 5 4 3 2
			3 4 7 8 9 10 11 12
. (15 D. D	N71		

<u>Steven P. Bye</u> in a field survey on November 11, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
  - West 1/4 corner of Section 34

Brehmer, 1930's set iron pipe in stones

12" tamarack N 5+ E, 19.7' Brehmer witnesses:

8" tamarack S 85+ E, 44.6"

6" tamarack S 6+ W, 20.3'

4.2' South of fence line East

L.C.R.C. File #206, Liber 1, Page 330, by Weinert, 6/15/76 states iron bar found with two (2) of Brehmer's witnesses found.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
  - West 1/4 corner of Section 34

2" i.d. iron pipe in stones and muck found, 10.5' North of fence line West, 9' East of fence line South, and on new fence line North.

Existing witnesses:

12" tamarack S 15 W, 20.62"

16" tamarack West 44.60'

4" Cedar S 15 E, 14.15'

APPROVED LAND CORNER P.A. 345 OF 1990 LEELANAU COUNTY

DATE: 10-5-94

10

COUNTY REP. M.M.O.Pu

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
  - G-12: West 1/4 corner of Section 34

2" i.d. iron pipe in stones accepted by the Leelanau County Remonumentation Peer Group, October 5, 1994, and replaced with a 3/4" i.d. galvanized iron pipe 3' long with a brass cap.

12" tamarack S 15 W, 20.62'

16" tamarack West 44.60'

4" cedar S 15 E, 14.25' 5" twin spruce N 43 W, 40.75'

Date November 16, 1999 Surveyor's Michigan License No. \_\_\_\_35991\_

STEVEN P BYE LAND SURVEYOR 35991

FORM APPROVED BY MICHIGAN STATE ROARD OF LAND SURVEYORS, JAN 28, 1971

REVISED JAN., 1983