

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in
LENAWEE COUNTY
(County)

Located In:

Corner Code **#**

1. Public Land Survey

T 55 R 2E

B-5

T _____ R _____

T _____ R _____

T _____ R _____

2. Property Controlling
in Section

S _____ T _____ R _____

S _____ T _____ R _____

3. Miscellaneous
Property in Sec.

S _____ T _____ R _____

S _____ T _____ R _____

Register of Deeds Stamp & File Number

4. Lot No. _____, Recorded Plat _____

5. Private Claims _____

I, Gary C. Bilow, in a field survey on March 21, 19 91, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

B-5: Corner established by Deputy Surveyor H. Parke in 1824 - accessories: W. Oak 18, N87-1/2E, 56; Y. Oak 6, N46W, 61. Michigan Department of Conservation Surveyor W. Lee Paddison shows on MDCS drawing (plan #E46A-1) dated Feb. 1959 "found stone and set 1" iron pipe with brass cap - accessories: N16.5E, 76.21', 13" Maple; S83E, 22.80', center 2" road sign post; S45.5W, 34.97', 8" anchor post." Corner recorded under Act 74, P.A. 1970 by Glenn Richard (RLS #13040) in Liber 1 Page 81 as "found spike over iron pipe - accessories: Michigan State Highway Department tag in RR tie post, N40W, 36.51'; MSMD tag in RR tie post, S50W, 34.68'; MSMD tag in RR tie post, S85E, 24.18'; MSMD tag in 14" Maple, N16.5E, 76.21'."

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-5: Found 1/2" iron bar in the intersection of Brix Road and Grassy Lake Road - recovered three witnesses from Glenn Richard. Accepted this corner as the best evidence of the original GLO corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

B-5: Found 1/2" iron bar in the intersection of Brix & Grassy Lake Roads
S85E, 24.40', nail & Michigan State Highway Department Tag in
railroad tie post
S50W, 34.72', nail & MSMD tag in railroad tie post
N16-1/2E, 76.30', double headed nail & tag in 22" Maple
N41W, 35.65', double headed nail & tag in fence post



Signed by

Gary C. Bilow

Date

5/20/91

Surveyor's Michigan License No.

26453

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971
REVISED MAY 14, 1975
REVISED JAN., 1983

PAGE 3

PAGE 2