

SURVEY & REMONUMENTATION

JAN 15 1998

Filed under Remonumentation Act 345 of 1990 LIBER 1 PAGE 203
LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

STATE OF MICHIGAN
LENAWEE COUNTY
FILED

For corners in

Lenawee

(County)

Located In:

Corner Code #

17 OCT 97 3:52 P.M.

VICTORIA J. DANIELS
REGISTER OF DEEDS

1. Public Land Survey

T-5-S R-2-E

A-1

T-5-S R-1-E

M-1

T- R-

T- R-

2. Property Controlling in Section

S- T- R-

S- T- R-

3. Miscellaneous Property in Sec

S- T- R-

S- T- R-

Register of Deeds Stamp & File Number

4. Lot No.

Recorded Plat

5. Private Claims

I, Glenn E. Richard

, in a field survey on May 19, 19 97

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

GLO 1815 Benj Hough set post corner T's 4&5 R's 1&2 E B. Oak 18 S 1/2 E 2.10 W. Oak 14 N 80 1/2 E 143 1967 I dug by hand through the pavement but didn't find anything. I set a iron pipe 33 feet west of found iron pipe and recorded it in L 5 P 59.
1973 Richard Gutekunst found iron pipe in monument box
1982 I found a iron pipe in a monument box and recorded it in L 5, P 59.
Sept. 24, 1996 I found iron pipe in monument box and witnessed it.
1996 Dean Gutekunst and Jackson Co. Rd. Comm. dug hole 6' +/- E-W by 8' +/- N-S but didn't find anything.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

May 19, 1997 Dean Gutekunst PS 18658 set a Harrison monument in a monument box in the base course of asphalt road.
May 28, 1997 I found Jackson Co. Harrison monument stamped PS 18658 in a monument box.
July 9, 1997 Dean Gutekunst P.S. 18658 recorded this corner under the Jackson Co. remonumentation program in L 1546, P 467, Jackson County Records.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Jackson Co. Harrison monument stamped 18658 and is the best available evidence of the position of the original corner.

"X" cut on face of N. gate post of chain link fence N 50° E 47.18
"X" cut on face of N. gate post of chain link fence S 80° E 38.24
"X" cut on face of S. gate post of chain link fence S 45° E 53.40
"X" cut on S. end C.M.P. S 80° W 59.67
"X" cut on N. end C.M.P. N 65° W 62.94

This corner is common with M-13, T4S, R1E, A-13 T4S, R2E, M-1, T5S, R1E

Ratified by Peer Group in accordance with P.A. 345

Co. Rep

Glenn E. Richard

Date June 3, 1997

Signed by

Glenn E. Richard
Glenn E. Richard

Date

Oct. 7, 1997

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 197

REVISED JAN, 198

ADAPTED FOR WORD PROCESSING MARCH 199

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

