

SURVEY &
REMONUMENTATION

NOV 07 1994

COMMISSION

Filed under Remonumentation Act 345 of 1990

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER 001 PAGE 32

For corners in

Lenawee

(County)

Located In:

Corner Code #

1. Public Land Survey

T - 6 - S R - 3 - E

E-3

T R

T R

T R

2. Property Controlling
in Section

S T R

S T R

3. Miscellaneous

S T R

Property in Sec.

S T R

4. Lot No. _____ Recorded Plat _____

5. Private Claims _____

I, Glenn E. Richard

, in a field survey on October 8 19 94,

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. January 1824, John Mack set post corner Sec 4, 5, 8 & 9, Elm 14 N 62 E 45, Elm 12 S 79 W 50

J.L. Richard records from early 1900's "Found sec corner in line with fence South".

July 1948, the corner appears to have been found (monument not described) B. Walnut S 45 E 39.5, corner fence post N 45 E 38.5, fence South 24'.

March 1976, I dug through the pavement with a back hoe and found a stone 2'-8" deep and raised to surface with a 3/4" X 2'-6" iron pipe and recorded it in L. 3, P. 424, Cut "X" on C.M.P. N 70° W 76.05

Cut "X" on C.M.P. S 30° W 17.75

Cut "X" on C.M.P. S 40° E 22.60

Dbl. hd. nail & disc in Elec. pole N 20° E 80.65

60 d spike in 16" Walnut N 75° E 114.72

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

October 8, 1994, Found 3/4" iron pipe in monument box, Replaced it with 3/4" X 3' iron pipe capped G.E.R., P.S. 13040. Stone still in place, hit with prod before setting 3/4" X 3' iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

3/4" X 3' iron pipe, (over stone) capped GER P.S. 13040 in monument box, and is accepted as the best available evidence of the position of the original corner.

Cut "X" (old one damaged) on C.M.P. N 70° W 76.14

Cut "X" (old one damaged) on C.M.P. S 30° W 17.22

Fd. "X" cut on C.M.P. S 40° E 22.60

Cut "X" on C.M.P. S 10° E 88.14

Fd. dbl hd. nail & disc in Elec pole N 20° E 80.60

Fd. 60d spike in 20" Walnut N 75° E 114.68

Ratified by Peer Group in accordance with P.A. 345

Signed by Glenn E. Richard

Glenn E. Richard

Co. Rep.

Glenn E. Richard

Date October 13, 1994

Date Oct. 20, 1993

Surveyor's Michigan License No. 13040

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975

REVISED JAN., 1983

ADAPTED FOR WORD PROCESSING MARCH, 1993

FILED

10:56 AM

OCT 28 1994

LENAWEE COUNTY
JEANETTE D. KNOX
REGISTER OF DEEDS

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													

