Filed under Remonumentation Act 345 of 1990

LIBER 001 PAGE 84

APR 0 1 1996

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

COMMISSION

For corners in

Lenawee	Located In:	Corner Code #	FILED NOW
(County)			
1. Public Land Survey	T <u>-7-\$</u> R <u>-2-E</u>	<u>K-12</u>	NOV 22 1995
	T R T R T R		LENAWEE COUNTY JEANETTE D. KNOX REGISTER OF DEEDS
in Section S	T R T R	Re	egister of Deeds Stamp & File Number
	T R T R		
			ABCDEFGHIJKLM
	corded Plat		1 2 6 5 4 7 8 9 10 11 12 5
		survey on <u>September 13</u> 19 95 ,	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned 7 in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the 8 current manual of survey instructions of the United States Department of the Interior, Bureau of Land			
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a 10 Court of Law; established, re-established, monumented, re-monumented, recovered, found as 11			10 30 29 28 27 26 25
expressed below:			12 31 32 33 34 35 • 36
NOTE: Not more than 4 coon this certificate.	orners, all in the same town	and range, may be recorded	13
A. Description of origina	I monument and accessories	and/or subsequent restoration:	

G.L.O., April 1824, John Mullett set 1/4 section post Hickory 6 S 61 E 25 Beech 10 N 38 W 54 Witnesses to corner were given to me by Mr. Clyde Anderson in June 1964. He told of watching some surveyors dig up the corner when he was a young man and he wrote down the witnesses in case he ever wanted the corner. In March of 1966 while doing some surveying for his estate, I dug through the pavement and found a stone. Raised with 1/2" iron pipe.

July 1993, Found iron pipe in pavement. Fd. dbl. hd. nail & disc in E.P. S 55° E 63.11, Fd. dbl. hd. nail & disc in E.P. S 45° E 32.86, Cut "X" on north end 12" C.M.P. N 55° W 49.12, Cut "X" on south end 12" C.M.P. S 75° W 48.51

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

September 13, 1995, Dug through new pavement and found 1/2" X 12" iron pipe in original pavement over stone surrounded by other stones. Drilled into stone and set 5/8" X 2' re-rod and set monument box.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

5/8" X 2' re-rod capped G.E.R. P.S. 13040 in monument box and is accepted as the best available evidence of the position of the original corner.

Dbl. hd. nail & disc in Elec. pole S 55° E 63.11 Dbl. hd. nail & disc in Elec. pole S 45° E 32.86

"X" cut on North end 12" C.M.P. N 55° W 49.12
"X" cut on South end 12" C.M.P. S 75° W 48.51

Re-rod on section line South 56.52

ole OF VICE GLENN E. CHAMOIR No. 13040 SONAL ST

Ratified by Peer Group in accordance with P.A. 345	Co. Rep. Alenn Kulara Date October 19, 1995
Signed by Glenn C Richard	Date Wov. 3,1995
Glenn E. Richard	
Surveyor's Michigan License No. 13040	FORM APPROVED BY MICHIGAN STATE BOARD OF LA