SURVEY & REMONUMENTATION

LUCE COUNTY REMONUMENTATION CORNER

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

Luce	Located In:	Corner Code ##	Flied 1/20 AD., 19 9	<u>5</u>
(Gounty)			At 12:30 o'clock P.	
1. Public Land Survey	T 45NR 9W	E-8	lihor D	MB.
	T R		Flle No. 2092 614	
	T R T R		tathy S. Ma	har
2. Property Controlling S	T R		Luce County Reg. of Deed	\$
	T R			
	T R		Register of Deeds Stamp &	File Number
Property in Sec. S	T R			
4. Lot No, Recor			A B C D E F G	HIJKL
5. Private Claims				ŢŢŢŢ
			3	ilili
	_		. 4	-10-11-12
Keith R. Waters in	a field survey onDeci	ember 2 19 92	5	
do hereby certify that under requirement in lines 1 and 2 above were in continuous	nents of P.A. 74, Michigan P.A. Iormance with regulations ar	. of 1970, the corner points mer ld rules therefore as required	of in the	15
current manual of survey instruction	is of the United States Depar	tment of the Interior, Bureau o	of Land 7	++++
Management or by a decree of a Cou above were in conformance with the				-222324
Court of Law; established, re-est	ablished, monumented, re-	monumented, recovered, for	und as	
expressed below: NOTE: Not more than 4 corner	re all in the came town a	nd rance may be recorde	30 7 29 20	272625
on this certificate.	5, an in the Same town at	no range, may be recorde	12 31 32 33	35 36
			13	
A. Description of original monu	ment and accessories and	d/or subsequent restoration	en:	
E-8 1/4 Corner C	ommon to Section	ns 20 & 21, T45M	I, R9W	OF MICKED
Original ties to	post: Beech 8.	N65°E 36 links	SIAIL	GAN
		S27°W 22 links		KEITH R. 🐪 🙀 WATERS
Found no evidence	of subsequent	restoration of t	this career	LAND
round no evidence	Ol Sanzedaette	restoration of i	ins corner. N* s	SURVEYOR *
			W.E	33142
	•		SED	MAID SURILLE
B. Description of corner evider	ice found and/or method	applied in restoring or ree	stablishing corner:	LAND 3000
E-8 (T45N, R9W)				
TI .				
This corner is be	ing re-establis	hed as part of t	the Luce County Remon	umentation
proportionate mea	surement on lin	orner. Re-estat e between sectio	olished corner by sin on corners 2638.24 fe	gle et north
and 2638.24 feet	south. Position	n works very wel	11 with an east-west	1/4 line
fence on the west	side of County	Road 399. Corr	ner falls on the east	side of
on the south side	rack road, on I	ine with blazed	and painted trees to	the west
on the south side	or a recentry	logged area.	tyteketu	Marie Carlotte Comment
		•	<i>y</i> *	·
			A_{ij}	-1.11
C. Description of monument for	r corner and accessories	actabliched to nernatuate	locating the position of the corner:	12/1/94
	Corrier and accessories	established to perperdate	iocating the position of the comer.	.coyee
E-8 (T45N, R9W)	an with a nlact	in on #00140	oproximately 15 feet	
the centerline of	a north-south	ic cap #33142 ap 2-track road. V	proximately 15 feet.	east of
8" Balsam Fir,		Note: Distance	es are to a nail and	tag in the
10" Red Pine, S 12" Red Pine, N		side of the tre	ee. Trees are blazed ings are compass bear	and
6" Red Maple, N		corrected for o	declination.	ings
Signed by Kett R 4	Jak.	Date _	12-23-94	
Surveyor's Michigan License No	33142		FORM APPROVED BY MICHIGAN STATE BOARD OF LAN	ND SURVEYORS, JAN. 28, 19 REVISED MAY 14, 19