

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce	Located In:	Corner Code #
(County)		
1. Public Land Survey	T R	
	T R	
	T R	
2. Property Controlling in Section	S 33 T 45N R 10W	F12
	S 33 T 45N R 10W	5
	S T R	
3. Miscellaneous Property in Sec.	S T R	
	S T R	
4. Lot No. , Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 5 05/09/2011 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(F12) Center of Section 33. 1977 - Established by Billy D. Buckler RLS at the intersection of 1/4 lines. Set 1"ID I.pipe with 4" aluminum cap. 16" Soft Maple S57W 22.1', 6" Soft Maple S74E 17.0'.

(5-Sec. 33) North 1/16 corner, Section 33. Not established in the original survey.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(F12) Found the 1977 monument in good condition and at record bearing and distance from the 1977 witness trees, both in good condition. Accepted the monument as a careful and faithful determination of the position of the corner.

(5-Sec. 33) Established the corner midway and on a straight line between Center of Section 33 1322.14' south and Quarter corner 1322.14' north.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(F12) Fd. 1"ID I.pipe with 4" aluminum cap.
Set measuring nail with MDNR tag in the side of:
21" Maple S56W 22.9' mrkd "CS" 1977 BT
7" Maple S73E 17.25 do do
5" Maple S22E 12.55' mrkd "CS BT"
9" Maple N03W 14.4' do
Bearings are magnetic.

(5) Set 1"IDx36" I.pipe with 4" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
5" Maple S65E 7.45' mrkd "N1/16 BT"
5" Maple S66W 19.75' do
29" Hemlock N26W 16.35' do
8" Maple N08E 29.8' do
Bearings are magnetic.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 06/15/2011

For the Michigan Department of Natural Resources, Forest Management Division

