LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 Luce County Remonumentation Corner

FEB 23 2001

For corners in

Corner Code # Luce County Located in: 1. Public Land Survey T45N R10W I-4/5 (North) Т R #007 T R Т R R 2. Property Controlling S Т Т S R in Section R 3. Miscellaneous S Property in Sec. S

SECTION

LUCE COUNTY REGISTER OF DEEDS

Recorded 3 paje 963 .ber 2-2001 09:47:40

Kathy S. REGISTER OF DEEDS

Register of Deeds Stamp & File Number

4. Lot No.

, Recorded Plat

5. Private Claims

I, Keith R. Waters, in a field survey on October 3, 2000 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

I-4/5 (North) Meander Corner Common to Sections 10 & 11, T45N, R10W, on the North Side of Twin Lakes

1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner at 1849 – Original corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner established by William Ives, 19.91 chains (918.06 feet) south of the ¼ corner established by Willia

Found no evidence of subsequent restoration of this corner.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

This corner is being reestablished as part of the Luce County Remonumentation Program. Found no evidence of the original corner. Reestablished corner on an old north-south fence line, at the proportionate north-south position according to the GLO notes between the section corner at I-5 to the south and the ¼ corner at I-4 to the north. Corner is 1728.0 feet north of I-5 (GLO is 1721.9 feet), 921.3 feet south of I-4 (GLO is 918.1 feet), and is 13.2 feet west of a straight line between said corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Placed a 1/2" x 48" rebar with a stamped aluminum Luce County Remonumentation cap at the corner location, which falls on an old north-south fence line, 40'± from the water's edge of Twin Lakes.

Nail and plastic witness tag #33142 in 9" Elm, N81°W 88.84" Nail and plastic witness tag #33142 in 6" Elm, N46°W 90.29' Nail and plastic witness tag #33142 in 7" Spruce, N23°W 101.36' Nail and plastic witness tag #33142 in 4° Scotch Pine, S19°E 145.41'

SINTE OF MICHIGAN KEITH R. WATERS PROFESSIONAL SURVEYOR No. 3 3 1 4 2 7,33142 લાઈ POPESSIONA

UMEN

Signed by Keith R. Water

Date 12 - 29 - 00

Surveyor's Michigan License No. 33142

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983 REVISED CCT., 1985

T45N R10W I-4-5N