

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

<u>Luce</u> (County)	Located In:	Corner Code #
1. Public Land Survey	T _____ R _____ T _____ R _____ T _____ R _____	_____
2. Property Controlling in Section	S <u>32</u> T <u>48N</u> R <u>10W</u> S _____ T _____ R _____ S <u>32</u> T <u>48N</u> R <u>10W</u>	<u>2</u> (GCDB 260200) <u>6</u> (GCDB 260160)
3. Miscellaneous Property in Sec.	S _____ T _____ R _____ S _____ T _____ R _____	_____
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 03/24/15 do hereby state
that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2
above were in conformance with regulations and rules therefore as required in the current manual of survey
instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of
a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with
the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established,
re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded
on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(2-Sec. 32) East 1/16 corner between Sections 29 and 32. Not previously monumented.

(6-Sec. 32) Northeast 1/16 corner, Section 32. Not previously monumented.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(2-Sec. 32) Established the corner midway and on the Section line between Section corner 1331.03'
east and Quarter corner 1331.03' west.

(6-Sec. 32) Established the position for the corner at the intersection of straight lines connecting
opposite 1/16 corners.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(2) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
10" Hemlock N85°W 1.27' mrkd "E1/16 BT"
11" Hemlock S45°W 20.10' do
7" Hemlock N06°W 11.70' do
6" Hemlock S87°E 22.34' do
E= 8109047.467 N= 194026.616

(6) Set 1"IDx28" I.pipe with 2" alum. MDNR cap.
Set measuring nail with MDNR tag in the side of:
7" Maple S48°E 4.92' mrkd "NE1/16 BT"
12" Maple N26°E 24.66' do
11" Maple N28°W 30.56' do
13" Y.Birch N83°W 14.05' do
E= 8109056.064 N= 193622.631



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RJ0491: N= 184295.153 m. E= 8114482.997 m.

Signed by Stephan J. Szyszkoski
Surveyor's Michigan License No. 33986

Date 04/28/2015

For the Michigan Department of Natural Resources, Forest Resources Division