

LAND CORNER RECORDATION CERTIFICATE
Filing Requirement of Act 74, Mich. P.A. 1970 as Amended

For corners in

Luce (County)	Located In:	Corner Code #
1. Public Land Survey	T 50N R 08W	D7 (GCDB 240400)
2. Property Controlling in Section	S T R	
3. Miscellaneous Property in Sec.	S T R	
4. Lot No. _____, Recorded Plat		
5. Private Claims		

Register of Deeds Stamp & File Number

1	A	B	C	D	E	F	G	H	I	J	K	L	M
2		6		5		4		3		2		1	
3													
4		7		8		9		10		11		12	
5													
6		18		17		16		15		14		13	
7													
8		19		20		21		22		23		24	
9													
10		30		29		28		27		26		25	
11													
12		31		32		33		34		35		36	
13													

I, Stephan J. Szyszkoski, in a field survey on 09/16/14 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

(D7) Quarter corner common to Sections 17 and 20. 1980 - Reestablished, monumented and recorded by Billy D. Buckler RLS. Restored corner midway and on line between two Section corners. Set 1" pipe with 4" alum. cap. 6" J.Pine S41°E 6.4', 5" Oak N64°W 28.2', 8" W.Birch S60°W 14.6'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(D7) Found the 1980 monument in good condition and at record bearing and distance from two of the three 1980 witnesses: The J.Pine S41°E is in good condition; the Oak N64°W is actually a Maple, in good condition with scribing visible; the W.Birch S60°W is now a stump. Left the monument in place and made new witnesses as described below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

(D7) Found 1"ID I.pipe with 4" alum. MDNR cap. Set measuring nail with MDNR tag in the side of:
6" Maple N56°W 28.19' mrkd "1/4S" 1980 NBT
11" J.Pine S41°E 7.00' do do
10" J.Pine N41°E 35.66' mrkd "1/4S NBT"
9" W.Pine S44°W 9.61' do
E= 8127368.777 N= 216948.405



Bearings are magnetic. Coordinates are MCS83 in meters, NAD83(2011) Epoch 2010.00 datum.
Coord. Ref.=NGS PID RJ1161: N= 217718.382 m. E= 8133488.614 m.

Signed by Stephan J. Szyszkoski Date 04/29/2015
Surveyor's Michigan License No. 33986

For the Michigan Department of Natural Resources, Forest Resources Division