SURVEY & REMONUMENTATION

FEB 2 4 1998

FILED

SE	CT	0	N
		•	

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

or corners in	r milg itequ	incline of Act 1-4,	1	J	1997 110V	13 h	; цц
LIVINGSTON (County)	Located In:	Corner Code#			REGISTE	HAVILAND R OF DEED IN COUNTY	I IS , MI.
2. Property Controlling Some in Section Some Some Some Some Some Some Some Some	T 1 N R 4 E T R T R T R T R T R T R T R T R T R T R	I-11		L.S.C.#	4	8843	
4. Lot No Recorded 5. Private Claims				A B C	D E F G	H I J	K L M
hat under requirements of P.A. 74, Michael under requirements of P.A. 74, Michael in conformance with regulations of the United States Department of Law and for that the corner poules of the Michigan Board of Land Sunonumented, recovered, found as expression. NOTE: Not more than 2 corners,	chigan P.A. of 1970, the corne is and rules therefore as rec intment of the Interior, Bureau pints mentioned in lines 3, 4 ar urveyors or by a Decree of a C	r points mentioned in line quired in the current m of Land Management or nd 5 above were in confo court of Law; established	es 1 and 2 above anual of survey by a decree of a surmance with the I, re-established,	3 4 - 7 5 6 - 18 - 7 8 - 19 - 9	-1716	-1011- -1514- -2223-	-12-
on this certificate.				10 30 11 12 31 13	-29 - 28	27 26-	36
Black Oak 20"	ment and accessories and Jampler, Deputy Surveyor South 01 degrees West 2 North 19 degrees West 1	2 links	oration:		PUTNAN	AIWF.	
B. Description of corner eviden	ICAL INFORMATION ON ce found and/or method a asphalt pavement at inte	applied in restoring o			ds.		
			<u>:</u>			Ý.	
Disk stamped "Livingst	corner and accessories e AM, replaced existing co ton Co. Monumentation Cosition of the original co	rner with 1¼" x 36" Corner, 19834" and is	iron pipe, affixed	l with 2" dia	. Brass disk.		
262 deg. 101.80' Set N	Nail / Tag N/S 36" Oak hail / Tag SE/S 24" Maple hail / Tag SE/S 12" Oak hail / Tag SE/S 24" Oak dia. Steel fence post dia. Steel fence post		PA 345 18 PEER GROUP REVIEWE SUBMITTE	ON 9-2	97 (UEO)	DED JED	P.C.
Signed bySurveyor's Michigan License No	19834		Date	<u>O</u>	CTOBER 6, 1	997	
⇒urveyors iviichigan License No	17834						

I-11, COMMON CORNER TO SECTIONS 26, 27, 34, AND 35

FIELD: 26 AUG 1994

FOUND 1-1/2" IRON PIPE 0.45' BELOW TOP OF ASTHRET AT FITHE INTERSECTION OF TOMA ROAD (SOUTH), PATTERSON LAKE ROAD (NORTH AND WEST), AND DARWIN ROAD (EAST). PIPE FALLS 3.0' WEST OF CENTERLINE PATTERSON LAKE ROAD (NORTH) AND 4.0' SOUTH OF CENTERLINE DARWIN ROAD. AREA APPEARS GOOD FOR GPS.

THE BY LONG COMPANIES OF THE STATE OF THE STATE OF

- 1825 Corner first set by Joseph Wampler, U.S. Deputy Surveyor at 80 chains from the south (P.7).
- 1870 Miles Bullock surveys between sections 26 and 27, measures 5296.50' south from I-9 (P.8).
- 1965 Garlock finds railroad spike, two witnesses are no longer in place, the other two check with found pipe (P.9-11).
- 1968 Atwell-Hicks surveys part of Southeast 1/4 section 27, no witnesses (P.12).
- 1971 Garlock finds iron pipe that replaced railroad spike, established new witnesses that are no longer in place (P.10,13).
- 1973 Stonerock survey finds $1 \frac{1}{2}$ " iron pipe with no witnesses and files Act 74. Records finding PK nail witnesses match Garlock's 1971 (P.14,16).
- 1974 Oscar Boss files Act 74, records a found bolt, witnesses are unique to all others (P.18).
- 1975 Oscar Boss finds PK nail, witnesses close to now found pipe (P.19).
- 1975 Garlock finds railroad spike, copied witnesses from the 1965 survey (P.20,21).
- 1981 Benton finds 3/4" iron pipe in pavement, witnesses check the now found pipe (P.23).
- 1982 Fahrner files Act 74 using 1975 Garlock witnesses (P.24).
- 1983 Gary Boss finds 1/2" iron pipe, witnesses check with now found pipe (P.25).
- 1994 Desine finds 1/2 " iron pipe, witnesses match the now found pipe (P.26).
- 1997 Herb Munzell identifies bolt as section corner in previous surveys he has performed, of which, we did not find in 1994. We requested information on this corner from Mr. Munzell, however no response or information was sent to us in 1994. New witness to this bolt added to this report.