LAND CORNER RECORDATION CERTIFICATE

For corners in	Filing Requi	irement of Act 74, Mich.	P.A. 1970 AUG ID 1 14 PM	54
Livingston (County)	Located In:	Corner Code ≠	NANCY HAVILAND REGISTER OF DEEDS LIVINGSTON COUNTY, M	(Ť
Public Land Survey	T <u>4</u> R <u>5</u> T R T R T R R	K-9	48843	
in Section S	T R T R		L.S.C.#214m	
	T R T R		Register of Deeds Stamp & File	e Number
-4. Lot No, Recor	ded Plat		———— АВС D E F G H	IJKL
=5. Private Claims				
Edward E. Anderson in			3 4 7 8 9 10-	11 12
do hereby certify that under requirent lines 1 and 2 above were in consumer to the current manual of survey instruction. Management or by a decree of a Coustove were in conformance with the Court of Law; established, re-est expressed below: NOTE: Not more than 4 corner	formance with regulations a is of the United States Depa rt of Law and/or that the corr rules of the Michigan Board ablished, monumented, re	and rules therefore as require artment of the Interior, Bureau ner points mentioned in lines 3, of Land Surveyors or by a Dec -monumented, recovered, fo	d in the of Land 7 4 and 5 8 19 20 21 22 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	23 24
on this certificate.		•	12 31 32 33 34	35 36
A. Description of original monu	ment and accessories ar	nd/or subsequent restoration	on:	
G.L.O. NOTES DATED MA G.L.O. WITNESSES W (W ()ak 18" \$25°W 31	Lks LKS RE	SURVEY &	
Deputy Surveyor Henry	/ Parker 1823-1825	i	SEP 2 6 1994	
ADDITIONAL HISTORICAL	DATA ON BACK OF	SHEET	COMMISSION	
B. Description of corner eviden	ce found and/or method	applied in restoring or ree	stablishing corner:	
Found 1/2" Rerod fit E.E.Anderson P.S., an		Engineer, Garlock	P.S.,	٠
PA 345 196	IO, APPROVED BY LIVING	STOM COLINATOR /		
	ON June 1, 1994 CO.	616111		
C. Description of monument for	corner and accessories	established to perpetuate	locating the position of the corner:	
Corner) 4' West N 17°W 80.46' Na N 79°E 86.68' Na S48°W 50.70' Na	Breakaway Pipe wof centerline Dea of centerline Dea oil S.E. side 14" oil S.Side 10" Elm oll N.Side 12" Waln	n Road walnut	ngston County Monument arker with red cap	
. 6		OF MONTH	APPROVED BY LIVINGSTON COUN MONUMENTATION PEER GROUP JUNE 1, 1994	TY

EDWARD E. ANDENSON SURVEYOR & ENGINEER

ENGINEER CYPENTER OF STREET

11495

Surveyor's Michigan License No. _

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

August 2, 1994

EDWARD E. ANDERSON, P.S., P.E. RICHARD F. FRANK, P.S. BRIAN R. SHALTZ, C.S.T.

Members of: Michigan Society of Professional Surveyors American Congress on Surveying and Mapping American Society of Civil Engineers

401 S. Leroy St. Fenton, Michigan 48430-2164

(313) 629-8974 FAX (313) 629-9069

May 10, 1994

SUMMARY

K-9 S.W. CORNER OF SECTION 24, T4N-R5E, DEERFIELD TOWNSHIP, LIVINGSTON COUNTY, MICHIGAN.

Found 1/2" rerod 4' west of the centerline of Green Road running North and South and the centerline of Dean Road running East and West.

Checked and measured to witnesses we found. Found all of Boss witnesses and they checked, Pages 10, 22, and 23, this dossier. Found three of Garlocks witnesses and they checked, Pages 12, 16, 18, 19, and 21, this dossier. Found E.E. Anderson and Pike witnesses which were the same and they checked, Pages 20 and 24, this dossier.

Distance from W 1/4 corner to the S.W. corner of said Section 24 is 2661.97' on Boss Survey and 2662.15' Garlock Survey and 2662.25' Garlock Survey, Pages 10, 17, 12, and 19, this dossier.

Distance from S 1/4 corner to the S.W. corner of said Section 24 is 2651.73' Boss Survey, Page 17, this dossier.

Made a clean sweep of immediate area and found no additional corners or irons.

Gravel Roads running North, South, East and West. All fairly flat.

Terrain is often to the South and the N.W. and slightly wooded to the $\rm N.E.$

Came to the conclusion that the 1/2" rerod we found is the correct S.W. corner of said Section 24.

Edward E. Anderson

P.S. #11495

EDWARD E.
ANDERSON
SURVEYOR &
ENGINEER
NO.
11495

Architectural, Construction, Property and Drainage Surveys Civil Engineering • Land and Site Planning • Mortgage Inspection Reports

Page 4

+ 50 6-4 4 50 CAL.