

SURVEY &  
REMONUMENTATION

MAR 13 1998

SECTION

1997 Mackinac County Remonumentation Corner

LAND CORNER RECORDATION CERTIFICATE  
Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

	<u>Mackinac</u> (County)	Located In:	Corner Code #
1. Public Land Survey		T42N R1W	G-10
		T___ R___	_____
		T___ R___	_____
		T___ R___	_____
2. Property Controlling in Section	S___	T___ R___	_____
	S___	T___ R___	_____
3. Miscellaneous Property in Sec.	S___	T___ R___	_____
	S___	T___ R___	_____

RECEIVED & FILED  
DIANE FRANKOVICH  
MACKINAC COUNTY CLERK OF DEEDS

DEC 18 1997  
AM PM  
7181511-1-1-13141516

Register of Deeds Stamp & File Number

4. Lot No. \_\_\_\_\_, Recorded Plat \_\_\_\_\_  
5. Private Claims \_\_\_\_\_

I, David B. Guthrie, in a field survey on July 7, 1997 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

	A	B	C	D	E	F	G	H	I	J	K	L	M
1													
2	6		5		4		3		2		1		
3													
4	7		8		9		10		11		12		
5													
6	18		17		16		15		14		13		
7													
8	19		20		21		22		23		24		
9													
10	30		29		28		27		26		25		
11													
12	31		32		33		34		35		36		
13													

A. Description of original monument and accessories and/or subsequent restoration:  
1845: G.L.O. Survey by J.H. Mullett - Set Post and Referenced-  
Tamarack 12 / N42W / 18  
Cedar 6 / S69E / 07

1973: Survey by Mary C. Fiendt - Fd. 1/2" Iron Bar.  
Referenced - N20°W - Power Pole - 128.40'  
N50°E - Traffic Signal Post - 64.63'  
S30°W - Traffic Signal Post - 48.95'

1981: Survey by Neil Hill - Found Pin in Monument Box.  
(CONT'D ON OTHER SIDE)

ACCEPTED BY THE MICHIGAN COUNTY  
SURVEY PEER GROUP AS THE  
OFFICIAL CORNER UNDER P.A.  
345 OF 1990 AT A MEETING  
HELD ON 11-21-97

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997: Remonumentation Survey by R.S. Scott Associates, Inc.  
Fd. 1/2" Iron Rod in Monument Box 5' North of C.L. M-134, in C.L. of 3 Mile Road.  
Referenced -  
(Exist.) N56°E - Utility Pole - 59.65'  
(Exist.) S66°E - 10" Spruce - 137.30'  
(Exist.) S23°W - Utility Pole - 66.60'  
(Exist.) S45°W - Utility Pole - 55.35'  
(Exist.) N10°W - Utility Pole - 128.06'

This corner position is compatible with County and local surveys. This corner position is accepted as a careful and faithful perpetuation of the position of the original corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1997: Placed 3" Mackinac County Cap stamped to identify the Corner over 1/2" Iron Rod  
Referenced -  
(Exist.) N56°E - Utility Pole - 59.65'  
(Exist.) S66°E - 10" Spruce - 137.30'  
(Exist.) S23°W - Utility Pole - 66.60'  
(Exist.) S45°W - Utility Pole - 55.35'  
(Exist.) N10°W - Utility Pole - 128.06'



Signed by David B. Guthrie  
Surveyor's Michigan License No. 22435

Date 12-12-97

SURVEY &  
REMONUMENTATION

MAR 13 1998

SECTION

(CONT'D FROM OTHER SIDE)

A. 1981: Survey by Neil Hill - Fd. Pin in Monument Box.

1986: Survey by Ronald Bischer - Fd. T-Iron in Mon. Box.

Referenced -

N60°W - 30" Spruce - 70.41'

N40°E - 12" Spruce - 59.94'

S39°E - Light Pole - 71.77'

1994: Survey by James H. Granger - Fd. T-Iron in Monument Box.

Referenced -

S26°E - P.P. - 69.31'

S73°W - P.P. - 77.86'

N27°W - P.P. - 59.76'

N52°E - 12" Spruce - 60.08'