

MICHIGAN  
DEPARTMENT OF CONSERVATION  
FORESTRY DIVISION

LAND CORNER RECORD

T...42... NR...12... W

...Mackinac... COUNTY

DESCRIPTION OF CORNER 1/4 corner between Sections 32 and 33

DESCRIPTION OF CORNER MONUMENT 1" Pipe with 4" Brass Cap

WITNESSES TO CORNER 10" cedar (1/4s NBT) N 68° E 37 1/2 Links

7" Cedar (1/4s NBT) S 68° W 48 Links

DESCRIPTION IN DETAIL AS TO HOW CORNER WAS LOCATED AND IDENTIFIED OR  
RESTORED. This corner was re-established midway between two Section corners.  
Found old cedar (down) with blazes facing corner.

Corner lies on East side of N - S road.

Corner was placed and witnessed September 18, 1959.

SURVEYORS SEAL

SIGNED Billy D. Buckler DATE 2/29/60  
REGISTERED LAND SURVEYOR  
Billy D. Buckler