

SURVEY & REMONUMENTATION

APR 28 1995

LAND CORNER RECORDATION CERTIFICATE

C152248

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

or corners in  
MACOMB

(County)

Located In:

Sterling  
Township

Corner Code ##

Public Land Survey

T 2N R 12E

F-3

Property Controlling

in Section

Miscellaneous

Property in Sec.

Lot No. , Recorded Plat

Private Claims

94 DEC 14 AM 10:53

RECEIVED  
REGISTERED  
DEEDS  
MICHIGAN  
JAN 17 1995

LIBER 6527 PAGE 825

Register of Deeds Stamp & File Number

Randy Kolehouse, in a field survey on June 28, 1994

hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as pressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

-3	1817	G.L.O.	Notes	Wampler	NA	Post
	1974	Survey	L. 2564 P. 449	Avey	#15396	1/2" Rebar
	1985	L.C.R.C.	L. 3836 P. 266 & 267	Ward	#22445	Iron Rod Btw. Rails E'ly Track
	1985	L.C.R.C.	L. 04723 P. 607	Donnelly	#21563	End. Iron
	1986	L.C.R.C.	L. 3945 P. 713	Avey	#30076	End. 1/2" Bar Btw. Rails E'ly Track
	1986	L.C.R.C.	L. 4077 P. 542	Kobs	#14097	1/2" Iron
	1990	L.C.R.C.	L. 04852 P. 258	Fenn	#23505	Iron Bar

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

-3	Found 1/2" rebar in center line of E'ly section of railroad track which checks Cert. Survey L. 2564 P. 449. L.C.R.C. L. 3836 P. 266 Center Line Top Nut on Hyd. S 55° E 81.34' Spk. and Washer T. Pole S 35° E 68.12' NE Bolt Crossing Signal S 25° W 90.56'	L.C.R.C. L. 4077 P. 1238 "+" Rim of Water Gate SE 60.08' Spk. and Cap P. Pole SE 57.38' Center Line NW Bolt RR Signal Base SE 57.39' "+" E End Conc. Curb SW 50.57'
	L.C.R.C. 4723 P. 607 Top Bolt Hyd. Az. 136° 81.38' Nail and Tag SW Face P. Pole Az. 145° 68.15' NE Bolt RR Gate Base Az. 205° 90.56'	L.C.R.C. L. 4852 P. 528 Center Line Top Hyd. Bolt SE 81.38' Nail SW Face Util. Pole SE 68.14' NE Bolt RR Crossing Gate SSW 90.56'
	Measure W. 2649.5 to E-3 (G.L.O. 2673) Measure E. 2664.9 to G-3 (Survey L. 2564 P. 447 = 2664.83) (G.L.O. 2673)	

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

-3	I replaced the found 1/2" Rebar with a 3/4" x 24" Iron Rod w/2" diameter Aluminum Cap stamped "Macomb County Monument MI Act 345 #25854." Center Line Top Nut of Hyd. S 88° W 41.95' NE Vertical Bolt RR Crossing Signal Base S 24° W 90.56' PK with Tag #22445 SW Face P. Pole S 35° E 68.14' PK S Face P. Pole S 87° E 62.07'
----	---

The selected location is accepted by me and is generally accepted by professional surveyors as the best available evidence of the position of the original corner.

ned by Randy J. Kolehouse

25854

Date 10/14/94

veyor's Michigan License No.

