## SURVEY & REMONUMENTATION

Surveyor's Michigan License No.

APR 2 8 19	LAND CORNER RECORDATION CERTIFICA	TE 0105003
For corners in COMMISS	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · · · · · ·
Macomb	Located In: Township Corner Code ##	10000000000000000000000000000000000000
(County)		Ol. Aug.
Public Land Survey	T 4 N R 12 E G-7	94 AUG -5 PM 1: 42
•	T R	CAPILOTER
	T R	REGISTER OF DEEDS MACOMB COUNTY, MI
	TR	MACOMB CHINEFTS
	T	and the state of t
	TR	•
	T R	Register of Deeds Stamp & File Number
Property in Sec. S		
4. Lot No Recor	ded Plat	ABCDEFGHIJKL
		2 - 5 5 3 2 1 -
	ì	3 + + + + + + + + + + + + + + + + + + +
Unaton V Vannady	June 15 94	4 - 7 - 4 - 9 - 10 - 11 - 12-
Huston K. Kennedy, in	a field survey on , 19 ,	5
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the		6 - 18 17 16 15 14 13 -
current manual of survey instructions of the United States Department of the Interior, Bureau of Land		7
Management or by a decree of a Cou	rt of Law and/or that the corner points mentioned in lines 3, 4 and 5	8 19 20 21 22 23 24
above were in conformance with the	rules of the Michigan Board of Land Surveyors or by a Decree of a ablished, monumented, re-monumented, recovered, found as	9
expressed below:	abiisned, monumented, re-monumented, recovered, round as	10 30 29 28 27 26 25
·	rs, all in the same town and range, may be recorded	11
on this certificate.	is, all in the same town and range, may be recorded	12 31 32 33 34 35 36
. On this continuate.	•	13
A. Description of original monu	ument and accessories and/or subsequent restoration:	
2.) 1979-Verba, P.S. #13603; LC	C L.3062, Pg.511 - Fnd 5/8" Iron Bar inside of Monument Bor RC L.3074, Pg.13 - Fnd 3/4" Rod in a Monument Box	
B. Description of corner evider	nce found and/or method applied in restoring or reestablish	ning corner:
1994 Kennedy Surveying, Inc has a bituminous surface,	Kennedy, P.S. #17623 - Fnd 5/8" Iron Rod in a Monument Bo 3.7' West of the centerline of Camp Ground Road, which has	x in the centerline of 29 Mile Road, which s a bituminous surface.
Witnesses from LCRC #1 wer	re used to recover and verify the location of the found 5/	8 <sup>n</sup> Iron Rod in a Monument Box.
FIELD MEASUREMENT BETWEEN	ACCEPTED BY THE MACOMB CO	UNITY SURVEY PEER
G-7 to F-7 2720.94 Feet	GROUP AS THE OFFICIAL CAPACITY OF 1900 AT	A COMPANY LIEU D
G-7 to G-8 2624.63 Feet	ON THE PARTY OF TH	Vac ce
	WILLIAM E. SODERBERG, P	.S., CHARMAN
C. Description of monument for	or corner and accessories established to perpetuate locating	g the position of the corner:
G-7 I replaced the found 5/8" I	Iron Rod in a Honument Box with 3/4" x 24" Iron Rod w/2" di	iameter aluminum cap stamped "Macomb County
CAPTH CHC JUA IN INCHIUM CAPTUR CO COL CAPTUR COLOR	" in a existing Monument Box. n. Washer SE face Power Pole	
	n. Washer NW face Power Pole	AND MINIME
N50°W 47.06' Set PK & Remo	n. Washer NE face Power Pole	WHATE OF MICHAINE
N45'W 49.30' Set PK & Remo	n. Washer East face 21" Haple	Mary & Branch of Carlotte
The selected location is accep	sted by me and is generally accepted by Professional Surve	yors as the best will able keridence of the
position of the original corne	r.	PROFESSIONAL SUBVEYOR

July 21, 1994

Date: