## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MANIS	TEE (County)	Located in:	Cor	mer Code ##	REGISTER'S OFFICE MANISTEE COUNTY
•	olic Land Survey	TENR TENR TENR TENR TENR	16 W W W W W W W W W W W W W W W W W W W	+ 5	AUG 1 6 1996  REGISTER OF DEEDS
in S ⊐3. Mis	Section scellaneous operty in Sec.	STR STR STR			Register of Deeds Stamp & File Number
		Recorded Plat			
<b>≡5</b> . Pri	vate Claims				
					4-7-8-9-10-11-2
Sammy S. Barnett in a field survey on May 14 1996, and hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned ain lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5.  Bove were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:					
	on this certificate	•			12 31 32 33 34 35 36
A. Description of original monument and accessories and/or subsequent restoration:					
M-13	Southeast Corner for Section 36, T22N, R16W, on the Township Line				
	Set Wood Post #1 White Pine 2 #2 White Pine 2 John Millerd, 2 Found Stake & V #3 White Oak 6	Yellow Pine BT " S63°E 321ks.(21.	52') 18.48')	E.W. Muencshi Found Stake	given 261ks.(17.17')  8" \$65°E 21.00' 10" \$N85°W 16.50' USFS Land Corner Record er, 1914, MCS
3. D	escription of corner	evidence found and/o	r method applied	in restoring or re	cotability Cottlet,
<b>■</b> -13	Southeast Corner for Section 36, T22N, R16W, on the Township Line #10 W.Oak 6" N80°W 29.18				
	On May 14, 1996, I found a 1" Iron Pipe, just above the surface of the ground, also found USFS tree tag witnessing this location, stamped D. H., March, 1973, found CCC crusier post S 78° E 34 feet, and the center line of two-track road lies 15 feet to the East, I Company no evidence to dispute his location for the Section Corner.  Corner.  according to the county plan adopted pursuant to P.A. 345 of 1990, as amended, (being the State Survey and Remonument Act, MCL 54.261 el. seq.). Date of Peer Review: ALIG 6 1996 Fullowy 70.				
	#1 Gone #2 Gone	•	Gone		#9 Found in good Condition
	#3 Gone		Same as 4		#10 Found in good condition
	#4 Gone	#7 #6	Same as 5	condition	·
#B Found in good condition  Description of monument for corner and accessories established to perpetuate locating the position of the corner:					
<b>≣-13</b>	Southeast Corner for Section 36, T22N, R16W, On the Township Line				
	corner.	o, and is accepted a	s a careful and	i faithful reest	dard Manistee County Monument, set flush ablishment of the position of themsioinal OF Michael
	(901 #2) MILL	e oak to 3 6 m	איים (פחם sbiki). מכיר	e in SE side of	tree)

White Pine 12" N 73° E 42.10'(60d spike in SE side of tree)
White oak 8" N 42° W 32.44'(60d spike in SW side of tree)
Black Oak 21" S 62° E 6.01'(60d spike in North side of tree)

Dat 1 . 2.1.

BARNETT

No.