

REMONUMENTATION

MECOSTA COUNTY REMONUMENTATION PROGRAM

CORNER APPROVED BY PEER GROUP ON SEPTEMBER 12, 1997

NOV 18 1997

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN
COUNTY OF MECOSTA
RECEIVED FOR RECORD

COMMISSION

Filing Requirement of Act 74, Mich. P.A. 1970

For corners in

MECOSTA

(County)

Located In:

Corner Code #

'97 NOV -7 P2:22

James Brown
REGISTER OF DEEDS

1. Public Land Survey T 15N R 10W G-02
T R
T R
T R
2. Property Controlling S T R
in Section S T R
3. Miscellaneous S T R
Property in Sec. S T R

- 4 Lot No. , Recorded Plat
5. Private Claims

Register of Deeds Stamp & File Number

I, JACK E. PIERSON, in a field survey on JUNE 19, 1997, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Only one corner may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

DEPUTY SURVEYOR, ABNER E. VANNESS, SET POST ON FEB. 14, 1838, AND WITNESSED:
8" IRONWOOD S06°E 22 LINKS
14" SUGAR N53°W 8 LINKS

MAY, 1961 - GEORGE BLASS, P.S. 5489, FILE NO. 730-61, SURVEY FOR CITY OF BIG RAPIDS OF ROSEN - HOOD AIRPORT, CALLS FOR WEST 1/4 CORNER AT END OF E-W 1/4 LINE FROM CENTER 1/4 CORNER. CORNER MONUMENT NOT IDENTIFIED, NO WITNESSES TAKEN. SURVEY IDENTIFIES FENCE LINE RUNNING EAST FROM 1/4 CORNER.

APPROVED BY MECOSTA CO. PEER GROUP
IN ACCORDANCE WITH P.A. 345 of 1990

James J. Knapke
CHAIRMAN

DATE

Sept. 12, 1997

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

1997, RETRACED E-W 1/4 LINE FROM CENTER 1/4 TO WEST 1/4 CORNER. POSITION CONFIRMED BY G. BLASS SURVEY IS A STEEL CORNER FENCE POST, WITH FENCE LINE RUNNING SOUTH, EAST AND WEST.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G - 2 1/4 CORNER COMMON TO SECTIONS 3 AND 4, T15N-R10W
ACCEPTED FENCE CORNER AS MOST PROBABLE POSITION USED BY BLASS. PHYSICAL SEARCH AND RECORD SEARCH REVEALS NOTHING TO CONTRADICT THIS CONCLUSION.

SET A STANDARD MECOSTA REMONUMENTATION MONUMENT AT BASE OF CORNER FENCE POST, AND IS ACCEPTED AS A CAREFUL AND FAITHFUL RE-ESTABLISHMENT OF THE POSITION OF THE ORIGINAL CORNER, AND WITNESSED:

STEEL FENCE POST WEST, 37.88 FEET
STEEL FENCE POST SOUTH, 20.50 FEET
8" BOX ELDER IN CLUMP EAST, 6.40 FEET
3" THORNAPPLE IN CLUMP AZ. 130°, 50.40 FEET

Signed by

Date

SEPTEMBER 10, 1997

Surveyor's Michigan License No.

19305

LIBER 100 PAGE 291

FORM APPROVED BY MICHIGAN STATE BOARD OF SURVEYORS FOR JAN. 28, 1971

ADAPTED FOR WORKING DURING MARCH, 1993

