

SURVEY & REMONUMENTATION REMON. COR. M-5, INGERSOLL TWP.
LAND CORNER RECORDATION CERTIFICATE
 Filing Requirement of Act 74, Mich. P.A. 1970

FEB 23 2001

524

For corners in
Midland (County)

SECTION

Located in: **Corner Code #**

1. Public Land Survey

T 13N R 2E M-5

T R

T R

T R

2. Property Controlling in Section

S T R

S T R

3. Miscellaneous Property in Sec.

S T R

S T R

4. Lot No. _____ Recorded Plat

5. Private Claims

I, **RODNEY CLAYPOOL**, in a field survey on August 3, 2000, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

M-5 Corner common to Sections 12 and 13 on East Townline

Survey by Glo, 1830's, set post
 Survey by M. Hunter, 1957, found 3/4" pipe
 Survey by D. Whittier, 1968, found
 Survey by J. Schafer, 1972, 1973, 1975, 1976, found 1/2" rod
 Survey by J. Jones, 1991, found 1/4" rod
 Survey by B. Ferguson, 1999, found
 LCRC by J. Schafer, 1972

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-5 Corner common to Sections 12 and 13 on East Townline

Found 3/4" pipe per surveys by M. Hunter, D. Whittier, J. Schafer, J. Jones, B. Ferguson and LCRC by J. Schafer.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-5 Corner common to Sections 12 and 13 on East Townline

Replaced pipe with 5/8" rod and brass cap stamped Midland Co. Remon Cor PS 29241 and is accepted as the best available evidence of the position of the accepted corner.


N 50 Deg E, 52.32, nail and disc in 24" Cedar (face) Rec. (53.6 centerline)
 N 25 Deg W, 59.93, nail in power pole. Rec. 59.82

S 50 Deg W, 108.63, spike in 36" Maple
 N 25 Deg E, 56.16, centerline telephone box
 N 45 Deg E, 106.63, Southwest corner brick house

A-5 T13N-R1E, North 13.18 ft.

According to Saginaw County Records, pages 407 & 408 corners should be common

	A	B	C	D	E	F	G	H	I	J	K	L	M
2	6	5	4	3	2	1							
3													
4	7	8	9	10	11	12							
5													
6	18	17	16	15	14	13							
7													
8	19	20	21	22	23	24							
9													
10	30	29	28	27	26	25							
11													
12	31	32	33	34	35	36							
13													



Signed by Rodney D. Claypool
 Surveyor's Michigan License No. 29241

Date 12-26-00
 Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971
 Revised May 14, 1971
 Revised Jan., 1983

APPROVED LAND CORNER
 P.A. 845 C 1990
 MIDLAND COUNTY

12/27/00 *[Signature]*